Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.
District II	OIL CONSERVATION DIVISION		30-025-34333
1301 W. Grand Ave., Artesia, NM 88210 <u>District III</u>	1220 South St. Francis Dr.		5. Indicate Type of Lease  STATE  FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u>	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)		TMBR 16 STATE  8. Well Number 1	
1. Type of Well: Oil Well Gas Well Other			
2. Name of Operator PATTERSON PETROLEUM LP			9. OGRID Number 141928
3. Address of Operator P.O. DRAWER 1416		10. Pool name or Wildcat	
SNYDER, TX 79550		SAUNDERS; PERMO PENN, EAST	
4. Well Location			
Unit LetterB:1250feet from theNORTH line and2176feet from theEASTline			
Section 16 Township 14S Range 34E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4128' GR			
Pit or Below-grade Tank Application ☐ o			
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUB  PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR			SEQUENT REPORT OF:  K
TEMPORARILY ABANDON	☐ CHANGE PLANS ☐ COMMENCE DRI		<del>_</del>
<del></del>	MULTIPLE COMPL	CASING/CEMENT	
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
Propose to plug & abandon well as for	ollows:	THE OIL	_ CONSERVATION DIVISION FOR ISS
1. Set 5" CIBP @12,200' w/20' cement on top. Circulate well with mud.  RE NOTIFIED 24 HOURS DRIOD TO THE			
2. Spot 25 sk in Centent plug 11,500 - 11,000			
3. Spot 40 sk "H" cement plug 10,300' – 10,100' BEGINNING OF PLUGGING OPERATIONS 4. Spot 40 sk "H" cement plug 9,100' - 8,900'			
5. Spot 40 sk "C" cement plug	7,000' - 6,800'		102922
6. Spot 40 sk "C" cement plug	5,800' - 5,600' 4,483' - 4,183' WOC & tag	ווג ברשון	83' NABABER 1828
7. Spot 50 sk "C" cement plug 8. Spot 40 sk "C" cement plug	1,500' - 1,300'	7353 - 770	
9. Spot 60 sk "C" cement plug	480' - 130'		The same of the sa
10. Spot 10 sk "C" cement plug	15' - 3'		Received
11. Cut off wellhead, weld on cap	& dry hole marker.		Hobbs &
			OCD S
			Received Hobbs OCD and belief. I further certify that any pit or below-
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE Plan	TITLE	_Engineer	DATE05/16/2007
Type or print name Nolan von Roe	der E-mail address	::	Telephone No. 325/573-1938
For State Use Only  MAY 2 2 2007			
APPROVED BY: A CONTROL OF HEIDIREPRESENTATIVE TO DATE			
Conditions of Approval (if thy):			

## PATTERSON PETROLEUM LP

