Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	•	WELL API NO.
District II	OIL CONSERVATION DIVISION	30-025-29500
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
District IV	Salita PC, INIVI 67505	6. State Oil & Gas Lease No. V-5490
1220 S. St. Francis Dr., Santa Fe, NM 87505		V-3490
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
	CATION FOR PERMIT" (FORM C-101) FOR SUCH	Carper McAlester ATE State
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number
1. Type of well. On well	Gas Well Guiel	2
2. Name of Operator		9. OGRID Number
Yates Petroleum Corporat	ion	025575
3. Address of Operator		10. Pool name or Wildcat
105 S. 4th Street, Artesia,	NM 88210	Eight Mile Draw; Abo
4. Well Location		
Unit Letter A:	660 feet from the North line and	660 feet from the East line
Section 25	Township 11S Range 34E	NMPM Lea County
Section 25	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	4142' GR	
Pit or Below-grade Tank Application		
		stance from nearest surface water
Pit Liner Thickness: mi		onstruction Material
12. Check	Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF U	ITENTION TO	OF OUT DEDON'T OF
		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON		ILLING OPNS. P AND A
PULL OR ALTER CASING	│ MULTIPLE COMPL │ CASING/CEMEN	T JOB 🔲
TOLL ON THE LET ON THE LET		_
	CT OTHER	
OTHER:	OTHER:	Re-Entry Operations
OTHER: 13. Describe proposed or com	pleted operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w		d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com	pleted operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion. 5-9-07 RU pulling unit. Spudded	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'.	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clean	pleted operations. (Clearly state all pertinent details, an york). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or com of starting any proposed w or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clean	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clesses. 5-14-07 PU 5-1/2" 17# casing and	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clesses. 5-14-07 PU 5-1/2" 17# casing and	pleted operations. (Clearly state all pertinent details, an york). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'.	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or come of starting any proposed was or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clesses of the starting and 5-15-07 to 5-19-07 Drilled and clesses of the starting and s	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.)	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clesses. 5-14-07 PU 5-1/2" 17# casing and	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.)	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or come of starting any proposed was or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of Section 1.	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.)	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion sx "C" Neat w/2% CaCl. WOC.
OTHER: 13. Describe proposed or come of starting any proposed was or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clesses of the starting and 5-15-07 to 5-19-07 Drilled and clesses of the starting and s	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.)	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion sx "C" Neat w/2% CaCl. WOC.
OTHER: 13. Describe proposed or come of starting any proposed was or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of Section 1.	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.)	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clees 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and clees Note: Well is completed in Abo 91 2-7/8" tubing @ 8844' I hereby certify that the information	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.) 17-9165' (existing perfs).	at give pertinent dates, including estimated date ttach wellbore diagram of proposed completion sx "C" Neat w/2% CaCl. WOC.
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clees 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and clees Note: Well is completed in Abo 91 2-7/8" tubing @ 8844' I hereby certify that the information	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.)	at give pertinent dates, including estimated date ttach wellbore diagram of proposed completion sx "C" Neat w/2% CaCl. WOC.
OTHER: 13. Describe proposed or come of starting any proposed was or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-14-07 RU pulling and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-14-07 RU pulling and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-14-07 Ru pulling and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-14-07 Ru pulling and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-14-07 Ru pulling and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-14-07 Ru pulling unit. Spudded and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-14-07 Ru pulling unit. Spudded and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-14-07 Ru pulling unit. Spudded and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-15-07 to	pleted operations. (Clearly state all pertinent details, an work). SEE RULE 1103. For Multiple Completions: A consumption on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.) 17-9165' (existing perfs).	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion sx "C" Neat w/2% CaCl. WOC. See and belief. I furth certify hat any pit of below- or an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clees 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and clees Note: Well is completed in Abo 91 2-7/8" tubing @ 8844' I hereby certify that the information	pleted operations. (Clearly state all pertinent details, an ork). SEE RULE 1103. For Multiple Completions: A on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.) 17-9165' (existing perfs).	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion sx "C" Neat w/2% CaCl. WOC. See and belief. I furth certify hat any pit of below- or an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-14-07 to 5-19-07 Drilled and cless of 5-15-07 Drilled and cless	pleted operations. (Clearly state all pertinent details, an work). SEE RULE 1103. For Multiple Completions: A consumption on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.) 17-9165' (existing perfs). 1 above is true and complete to the best of my knowledger closed according to NMOCD guidelines , a general permit TITLE Regulatory Compliance.	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion sx "C" Neat w/2% CaCl. WOC. The second proposed completion of
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-15-07 to 5-19-07 Drilled and cless of 5-18" tubing @ 8844" I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	pleted operations. (Clearly state all pertinent details, an work). SEE RULE 1103. For Multiple Completions: A consumption on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.) 17-9165' (existing perfs). 13-9165' (existing perfs). 14-9165' (existing perfs). 15-9165' (existing perfs). 16-9165' (existing perfs). 17-9165' (existing perfs).	ance Technician Telephone No. 505-748-1471
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-14-07 to 5-19-07 Drilled and cless of 5-15-07 Drilled and cless	pleted operations. (Clearly state all pertinent details, an work). SEE RULE 1103. For Multiple Completions: A consurface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.) 17-9165' (existing perfs). 13-9165' (existing perfs). TITLE Regulatory Compliance of the performance of the perfo	ance Technician Telephone No. 505-748-1471
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-15-07 to 5-19-07 Drilled and cless of 5-18" tubing @ 8844" I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	pleted operations. (Clearly state all pertinent details, an work). SEE RULE 1103. For Multiple Completions: A consurface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.) 17-9165' (existing perfs). 13-9165' (existing perfs). TITLE Regulatory Compliance of the performance of the perfo	ge and belief I furthese til hat any pit of below- or an (attached) alternative OCD-approved by an Incom_Telephone No505-748-1471
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and clees 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and clees Note: Well is completed in Abo 91 2-7/8" tubing @ 8844' I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Stormi Defor State Use Only APPROVED BY:	pleted operations. (Clearly state all pertinent details, an work). SEE RULE 1103. For Multiple Completions: A consumption on surface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.) 17-9165' (existing perfs). 13-9165' (existing perfs). 14-9165' (existing perfs). 15-9165' (existing perfs). 16-9165' (existing perfs). 17-9165' (existing perfs).	ge and belief I furthese til hat any pit or below- or an (attached) alternative OCD-approved plan ance Technician PATE PATE DATE DA
OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 5-9-07 RU pulling unit. Spudded of 5-10-07 to 5-13-07 Drilled and cless of 5-14-07 PU 5-1/2" 17# casing and 5-15-07 to 5-19-07 Drilled and cless of 5-15-07 to 5-19-07 Drilled and cless of 5-18" tubing @ 8844" I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	pleted operations. (Clearly state all pertinent details, an work). SEE RULE 1103. For Multiple Completions: A consurface plug. Drilled and cleaned out to 2900'. aned out to 5-1/2" stub @ 4385'. slip joint. Tagged stub and slipped over. Pumped 128 aned out to 9850'. (Drilled out CIBP @ 9075'.) 17-9165' (existing perfs). 13-9165' (existing perfs). TITLE Regulatory Compliance of the performance of the perfo	ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion sx "C" Neat w/2% CaCl. WOC. The second of the