16 m

Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

_		
	Lease Serial No.	

SUNDRY NOTICES AND REPORT	NM-61869			
Do not use this form for proposals to dril abandoned well. Use Form 3160-3 (APD)	6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE- Other instruction	7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well Gas Well Other	9 Wall Name and No.			
	8. Well Name and No. Cotton Draw Unit #28			
2. Name of Operator Pogo Producing Company	9. API Well No.			
3a Address 3b F	30-025-08206			
P. 0. Box 10340, Midland, TX 79702 43	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Paduca Delaware			
	11. County or Parish, State			
1980' FSL & 1980' FEL, Section 21, T25S, R32E	Lea County, NM			
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION TYPE OF ACTION				
× Notice of Intent Alter Casing Fra	epen Production (St cture Treat Reclamation w Construction Recomplete	Art/Resume)		
Change Plans    Change Plans   X Plug and Abandon   Temporarily Abandon				
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  1. Move in open top pit to circulate into. 2. Set CIBP @ 4575'. 3. Circulate hole w/ mud. 4. Cap CIBP w/ 30 sks cmt to cover Base of Salt. 5. Perforate casing at 1,300'. 6. Sqz perfs w/ 45 sks cmt. 7. Tag top of plug @ 1,050' – 50' above top of Salt. 8. Perforate casing @ 400'. 9. Sqz perfs w/ 150 sks cmt. Circ cmt to surface. 10. Cut off head & install dry hole marker.				
14. Ihereby certify that the foregoing is true and correct Name (Printed/Typed) Cathy Wright	Title Sr. Eng	Tech		
Signature Off Signature	Date 05/21/07	APPROVED		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by	Title	Date MAY 2 2 2007		
Conditions of approval, if any, are attached. Approval of this notice does not	<del>  </del>	re M hou all		
certify that the applicant holds legal or equitable title to those rights in the sul which would entitle the applicant to conduct operations thereon.	Office	WESLEY W. INGRAM		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)