Firm 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

NMLC065151

SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well 8. Well Name and No. Oil Well Gas Well Other **BROWN 51 #02** 2. Name of Operator 9. API Well No. Orbit Petroleum, Inc. 30025-21703 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 1131 East Britton Road; Oklahoma City, OK 73131 Sawyer - San Andres (405) 607-6020 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Section: NMNM19 Township: 9S Range: 38E Meridian: NMP County: Lea State: NM LEA, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen ✓ Notice of Intent Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Other Test Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Complete MIT, purpose is to verify well bore integrity. Base on positive test we will submit procedures to rework & re-activate well. - Wire line company to move on site. - Water truck on site. - Run wire in hole to test TD & verify. - Fill bore with fluid, pressure up & test for leaks. - Verify casing integrity. - Move off well site - Estimated time for procedure is 1/2 day. Procedures estimated to be completed on or before July 15, 2007. or plane to , and a submitted. act be online 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Jim Frazie Title President Signature Date 05/17/2007 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by PETROLEUM ENGINEER MAY 2 4 2007 Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct the stight 2, make it a crime for any person knowled APPROVED FOR MONTH PERIOD Title 18 U.S.C. Section 1601 and Title 43 U. fictitious or fraudulent state thanks or fraudulent state thanks or fraudulent. (Instructions on page 2)

ENDING