

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
1625 N. French Dr.
Hobbs, NM 88240

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

Injection

2. Name of Operator

OXY USA WTP Limited Partnership

192463

3a. Address

P.O. Box 50250, Midland, TX 79710-0250

3b. Phone No. (include area code)

432-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330 FSL 330 FWL SWSW(M) Sec 4 T24S R37E

5. Lease Serial No.

NM7488

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or
Myers Langlie Mattix Unit

8. Well Name and No.

181

9. API Well No.

30-025-10999

10. Field and Pool, or Exploratory Area
Langlie Mattix 7Rvr Qn-GB

11. County or Parish, State

Lea NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

08/06/2003 CMIC: Davis

MIRU KEY plugging crew #83 NDWH NU BOP RIH tagged cmt @ 3355'. SION

08/07/2003

RU pumped 50 bbls mud had to repair cmt pump. SION

08/08/2003

Spotted 30 sx Class C cmt POOH to 2689 spotted 30 sxs class C cmt. POOH w/ tbg WOC. RIH tagged cmt @ 2523'. POOH to 1233 spotted 25 sxs class C cmt. SION Reviewed and cmt tag witnessed by BLM rep Marlin Deaton.

08/09/2003

RIH tagged cmt @ 926' POOH to 395 perf csg. Brokedown perfs had returns to surface. POOH w/ tbg ND BOP NU WH. Pumped 125 sxs class C cmt leaving 5-1/2 csg full circulating cmt to surface between 5-1/2 and 8-5/8 csg.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

David Stewart

Title

Sr. Regulatory Analyst

Date

9/19/03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Larry W. Wink

Title

OC DISTRICT SUPERVISOR/GENERAL

Date

SEP 29 2003

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office