Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103 Revised March 25, 1999	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210				30-025-09251	
District III 1220 South St. Francis Dr.			5. Indicate Type of Lease STATE FEE X		
1000 Rio Brazos Rd., Aztec, NM 87410				6. State Oil & Gas Lease No.	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505				o. State Off &	Jas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name of	r Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				J F Janda NCT-J	
PROPOSALS.) 1. Type of Well:					
Oil Well X Gas Well Other				9 Wall No. 1	
2. Name of Operator Gruy Petroleum Management Co.				8. Well No. 1	
3. Address of Operator				9. Pool name or Wildcat	
P.O. Box 140907, Irving, TX. 75014-0907				Jalmat-Tnsl-Yts-7RV	
4. Well Location					
Unit Letter I - 1650 feet from the South - line and 990 feet from the East line					
Section 04 Township 25 S Range 37E NMPM Lea County 10. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3497' GR					
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN				SEQUENT RE	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	K X	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN	ND 🗆	ADAMOONMENT
OTUED					
OTHER:			OTHER: Return		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or					
recompilation. Ru Pooh with parted tbg. And rods. PU 6 1/4 " bit and scrapers, ru foam air unit, clean out wellbore to 3750' (perfs 3129'-3750').					
Hit bridges @ 3146',3174', & 3465'. Rih with packer, set @ 3066', Acidize well with 3,000 gal. Of 15 % Hcl/3000# of rock salt. Pooh					
with packer, rih with Production tbg. (106 Jts. 23/8" J55), SN, Perf Sub, OE MA. SN set @ 3303'.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE LIGGILLES	TI TI	TLE	Production Superin	tendent	DATE_9/31/03
Type or print name Reggie Res	ton		Telephone	No. 505-393-23	58
(This space for State use)	. 1 1 001	SIGTOIC	T SUPERVISOR/GI	ENIEDAL MANIACI	EN OCTAGOGG
APPPROVED BY Lary L	1 / 1 / 1	TLE			ER OCT 02 2003
Conditions of approval, if any					155 X
>				//	AF" ASS
				100	
				<i>(€</i>	2 2003
					Olil "FED
ドースのから					
					, oco