

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-32031
5. Indicate Type of Lease STATE FEE X
6. State Oil & Gas Lease No.

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well X Gas Well Other	7. Lease Name or Unit Agreement Name:  Shell "B" State Com.
2. Name of Operator Gruy Petroleum Management Co.	8. Well No. 1
3. Address of Operator P.O. Box 140907, Irving, TX. 75014-0907	9. Pool name or Wildcat Eumont-Yates-7RV-Queen
4. Well Location  Unit Letter M - 660 feet from the South - line and 660 feet from the West line Section <sup>32</sup> <del>31</del> Township <sup>20</sup> <del>25</del> S Range 37E NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3537' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK	X	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>		PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>		
OTHER:		OTHER: Plans, to PA well bore		

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Attempt to TA well, Ru WL rih obtain BHP (126 PSI), Tag PBTD @ 3270'. RU rig, pooh with 105 Jts. 2 3/8" tbg. + 8' piece. Ru WL, Rih with 3.62" G-ring, tag @ 2955', Call Gary Wink, NMOCD to as for approval to set Cibp @ 2952', (Perf. 3307-3487'). Permission granted, Set CIBP @ 2882', spot 35' of class H cement on plug. No fluid seen in well bore. Pump 41 bbls of treated Water to pressure test casing, pump .33 BPM @ 500 Psi, would not pass pressure test. Well will be scheduled to be PA'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Reggie Reston TITLE Production Superintendent DATE 9/31/03  
Type or print name Reggie Reston Telephone No. 505-393-2358

(This space for State use)

APPROVED BY Gary W. Wink OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE OCT 02 2003  
Conditions of approval, if any

