Submit 3 Copies To Appropriate District Office <u>District 1</u>	Energy, Minerals and Natural Resources		Form C-103 May 27, 2004 WELL API NO.
1625 N French Dr, Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S St Francis Dr, Santa Fe, NM 8750	OIL CONSERVAT 1220 South St. Santa Fe, NI	Francis Dr.	30-025-00542 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.
	TICES AND REPORTS ON WE DISALS TO DRILL OR TO DEEPEN OF	R PLUG BACK TO A	7. Lease Name or Unit Agreement Name: MalMar Unit
1. Type of Well: Oil Well Gas Well Other WIW			8. Well No. 101
2. Name of Operator			9. OGRID Number
Mar Oil and Gas Corp			151228 10. Pool name or Wildcat
3. Address of Operator PO Box 5155, Santa Fe,	NM 87502		Maljamar Grayburg/ San Andres
4. Well Location			
Unit Letter A: 660 feet from the North line and 660 feet from the East line			
Section 13 Township 17S Range 32E NMPM County Lea			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application or Closure Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
	Appropriate Box to Indicat		
			_
	NTENTION TO:	L L	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	」 PLUG AND ABANDON ☐] CHANGE PLANS ☐	REMEDIAL WORK	
PULL OR ALTER CASING		CASING/CEMENT	
_	COMPLETION		-
OTHER:	П	OTHER:	
			ve pertinent dates, including estimated date of
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
recompletion.			
5/29/07 RIH w/ tbg. Tagged CIBP @ 4163'. SDFN			
5/30/07 Spot 25 sx. cmt plug @ 4163 to 2916. Circulated hole with mud laiden fluid. Perf. csg @ 2477. RIH w/ pakcer and Sqz.			
50 sx cmt. WOC 4 hrs. Tagged plug @ 2360. SDFN 6/01/07 Perf. csg @ 1200. Set packer @ 900'. Sqz. 50 sx. cmt. WOC 4 hrs. Tag plug @ 1080'. Perf. Csg. @ 350'. Pack off			
wellhead and Circulated 120 sx. cement to surface inside and out. Cut off wellhead, Install Dry Hole Marker, Clean loc. Rigged			
down.			121314151677
•			NOTE STEEL
			istall Dry Hole Marker Clean loc. Rigged
			25 20 100 100 150 150 150 150 150 150 150 15
Appr	oved as to plugging of the W	ell Bore.	To bowing Multi
Liability under bond is retained until			(2)
surfac	e restoration is completed.		
			128293037
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE Bully	E. Fruham TITI	E Foreman	DATE 6/15/07
Type or print name Billy E. Prichard E-mail address: DATE 6/15/07 Type or print name Billy E. Prichard E-mail address: Telephone No. 390-9100			
Type or print name Billy E. Prichard E-mail address: Telephone No. 390-9100 For State Use Only OC FIELD REPRESENTATIVE MUSTAFF MANAGER			
	, , , , , , , , , , , , , , , , , , , ,		
APPROVED BY Havy	W. Wind TITI	_E	DATE
Conditions of Approval (if any):		Francisco de la bro	JUN 2 8, 2007