Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I 1625 N French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resource	WELL API NO.
District II 1301 W. Grand Ave, Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-23719
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr., Santa Fe, NM 87505		
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO	CES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	,
1. Type of Well: Oil Well X	Gas Well Other	8. Well Number 1
2. Name of Operator Chesapeake	Operating Inc.	9. OGRID Number 147179
3. Address of Operator 2010 Rankin Hwy		10. Pool name or Wildcat
Midland,	TX 79701	Vacuum; Abo Reef
4. Well Location		
Unit Letter C: 990 feet from the North line and 1890 feet from the West line Section 19 Township 17S Range 36E NMPM CountyLea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	3891 GR	
Pit or Below-grade Tank Application or Closure		
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
• • •		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	<u> </u>	E DRILLING OPNS. □ P AND A 🛛
PULL OR ALTER CASING		EMENT JOB
OTHER:	☐ OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
2/7/07. MIRU plugging unit and surface equipment, unhang, work w/stuck pump back off rods, strip OOH. 2/14/07. Tag plug @1735, POOH w/tbg, POOH w/WL, perforate @385, RIH w/pkr set @52, squeeze 70 sx @385, WOC, tag @235, ND BOP, set plug @60-surface, Install dry hole marker. Well is P&A.		
To bot, set plag @ 00-satistee, in 2017 2017 2017 2017 2017 2017 2017 2017	App Liab	roved as to plugging of the Well Bore. ility under bond is retained until ace restoration is completed.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed/or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan		
	- · · · · · · · · · · · · · · · · · · ·	
SIGNATURE SIGNATURE	TITLE Regulatory Tech	
Type or print name Shay Stricklin For State Use Only	E-mail address;sstrickl	1 HIN 2 8 2007
APPROVED BY: Lay 1)	Wink OCHHIELD REPRESENTAT	IVE II/STAFF MANAGER DATE
Conditions of Approval (if any):	O HUBBY ISSUED	DATE