+Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C 103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM S8240 **OIL CONSERVATION DIVISION** WELL API NO. P.O. Box 2088 30-025-09237 Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE DISTRICT T11 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE •APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Well X OTHER State A A/C 1 2. Name of Operator 8. Well No. Raptor Reser 35 3. Address of Operator 9. Pool name or Wildcat 901 Jalmat Tansill Yates 7 Rvrs (Gas)79240 South 990 Unit Letter L Feet From The Line and Feet From The \_\_\_ Section Township Range 36E **NMPM** County 10. Elevauon (Show whether DF, RKB. RT, GR, ctc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER\_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Raptor Resources, Inc plans to temporary abandon the above listed well: GIH Set CIBP 100' above perfs. Run a casing intergerty test with chart The OCD will be notified 24 hrs prior to the testing of the well. **Agent For Raptor Resources** 9-29-03 TYPE OR PRINT NAME Bill R. Keathly OC DISTRICT SUPERVISOR/GENERAL MANAGER