

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-20936
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator MARBOB ENERGY CORPORATION		6. State Oil & Gas Lease No. E-9721
3. Address of Operator PO BOX 227, ARTESIA, NM 88211-0227		7. Lease Name or Unit Agreement Name NEW MEXICO "CR" STATE
4. Well Location Unit Letter <u>P</u> : <u>885</u> feet from the <u>SOUTH</u> line and <u>885</u> feet from the <u>EAST</u> line Section <u>32</u> Township <u>19S</u> Range <u>32E</u> NMPM County <u>LEA</u>		8. Well Number 2
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3532' GL		9. OGRID Number 14049
		10. Pool name or Wildcat LUSK; STRAWN

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PLUG & ABANDON AS FOLLOWS:

8/13/03 - SET 4 1/2" CIBP @ 10600' W/ 30' CMT ON TOP OF PLUG.
8/15/03 - CUT 4 1/2" CSG @ 7303'. COULDN'T PULL.
8/19/03 - SET 4 1/2" PKR @ 7000'. SQZ 50 SX CLASS "C" NEAT CMT. WOC 4 HRS.
TAGGED CMT @ 7210'. CUT 4 1/2" CSG @ 3902'. PULLED & LAID DOWN.
8/20/03 - RIH. OPEN END W/ 3950' TBG. SPOT 50 SX CLASS "C" NEAT CMT.
8/21/03 - RIH. TAGGED CMT @ 3763'. SPOT 75 SX CLASS "C" NEAT CMT @ 2550'. WOC 4 HRS. TAGGED CMT @ 2500'. SPOT 75 SX CLASS "C" NEAT CMT @ 2500'.
8/22/03 - RIH TO 2500'. NO FILL, SPOT 75 SX CLASS "C" NEAT CMT. WOC 4 HRS. TAGGED CMT @ 2100'. PERF 8 5/8" CSG @ 975'. SET PKR @ 850'. SQZ W/ 75 SX CLASS "C" NEAT CMT.
8/26/03 - RIH. TAGGED CMT @ 860'. PERF 8 5/8" CSG @ 400'. SET PKR @ 60'. SQZ W/ 75 SX CLASS "C" NEAT CMT. WOC 4 HRS. TAGGED CMT @ 287'. PERF 8 5/8" CSG @ 60'. CIRC CMT ON 8 5/8" CSG.
8/27/03 - CUT OFF WELL HEAD. INSTALL DRY HOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Diana J. Cannon TITLE PRODUCTION ANALYST DATE 10/1/03

Type or print name DIANA J. CANNON Telephone No. (505) 748-3303
(This space for State use)

APPROVED BY Harry W. Wink TITLE DISTRICT SUPERVISOR/GENERAL MANAGER DATE OCT 03 2003
Conditions of approval, if any:

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.