

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-005-~~20002~~ 20023
5. Indicate Type of Lease
STATE ☒ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG-BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

CANO PETROLEUM

3. Address of Operator

801 Cherry St suit 3200 unit 25 Fort Worth TX 76102-6882

4. Well Location

Unit Letter F : 1980 feet from the N line and 1980 feet from the W line
Section 16 Township 8S 31 Range 30E NMPM County CHAVEZ

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7-8-07 MIRU equipment RIH w/ 3-3/4 bit tag fill @ 576 POOH w/ 2 jts shut well in SDON

7-9-07 RIH tag up @ 581 drill out bridges down to 1293 found bad spot in csg worked down to 1389 POOH w/ tbg shut well in SDON

7-10-07 RIH w/ csg swage worked through bad spot @ 1293 POOH w/ swage RIH w/ bit drilled down to 2576' PUH to 919' SDON

7-11-07 RIH w/ tbg ,DC ,& bit tag fill @2016 drill down to 2753' getting mud in returns POOH w/ tbg shut well in SDON

7-12-07 lay down tbg and tools RD equipment move off location

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Gene Brookshire

TITLE Production Foreman DATE 7-13-07

Type or print name Gene Brookshire

E-mail address:

Telephone No. 505-513-0286

For State Use Only

APPROVED BY:

Larry W. Wink

TITLE OCD FIELD REPRESENTATIVE II/STAFF MATERIALS DATE JUL 16 2007