Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N French Dr, Hobbs, NM 87240 30-025-09310 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave, Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE X FEE \square Santa Fe, NM 87505 1000 Rio Brazos Rd, Aztec, NM 87410 District IV 6. State Oil & Gas Lease No. 1220 S. St Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A State A A/C 1 DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Gas Well 🗷 Oil Well Other 9. OGRID Number 2. Name of Operator 194849 Petrohawk Operating Co. 10. Pool name or Wildcat 3. Address of Operator Jalmat; Tan-Yates-7 RVRS (GAS) 1000 Louisiana, suite 5600, Houston, TX 77002 4. Well Location 990 NORTH 1650 feet from the line and ___ __ feet from the_ line Unit Letter **NMPM** Township 235 Range LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3430' GR Pit or Below-grade Tank Application . or Closure Pit type _____ Depth to Groundwater _ _ Distance from nearest fresh water well _____ Distance from nearest surface water _ Pit Liner Thickness: Below-Grade Tank: Volume _bbls; Construction Material . 12. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REMEDIAL WORK PERFORM REMEDIAL WORK 🗷 PLUG AND ABANDON ALTERING CASING COMMENCE DRILLING OPNS. | PLUG AND CHANGE PLANS TEMPORARILY ABANDON ABANDONMENT CASING TEST AND PULL OR ALTER CASING **MULTIPLE CEMENT JOB** COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. See Attched Procdure and Wellbore diagram. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed of closed according to NMOCD guidelines _____, a general permit _____or an (attached) alternative OCD-approved plan _____ Production Analyst **SIGNATURE** _ TITLE_ _ DATE_ E-mail address: Svaughn@petrohawk.com Type or print name Sheila Vaughn Telephone No. For State Use Only

JUL 1 8 2000

APPROVED BY_

Conditions of Approval, if any:

Sheila Vaughn

Subject: RE:

State A A/C-1 #29

- 1. Pull production equipment.
- Cleanout openhole interval to 3600'.
 Run and cement 4-1/2" casing from 3600' to surface.
- 4. Perforate, acid and frac the Yates, Seven Rivers, Langlie Mattix and Queen.
- 5. Clean out well. Rerun production equipment and produce all zones together per Administrative Order DHC-3913.



