

New Mexico Oil Conservation Division, District I

1625 N. French Drive
Hobbs, NM 88249
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

LC-068288B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

ROCK QUEEN SAND UNIT

8. Well Name and No.

64

9. API Well No.

30-005-00860

10. Field and Pool, or Exploratory Area

08559 CAPROCK QUEEN

11. County or Parish, State

CHAVES COUNTY, NM

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well

☐

Oil Well

☐

Gas Well

☒

Other

2. Name of Operator
CELERO ENERGY II, LP

3a. Address

400 W. ILLINIOS, STE 1601, MIDLAND, TX 79701

3b. Phone No. (include area code)

432-686-1883

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SEC. 25, T13S, R31E, Unit Letter N
660' FSL & 1980' FWL

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other RE-ACTIVATE
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	INJECTION WELL
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. MIRU Well Service Rig
2. TOOH w/ injection tbg
3. Clean out well to TD
4. Test casing w/ packer
5. Deepen well 20'
6. Run compensated Neutron log
7. Run Bond log & Casing Inspection log
8. TIH w/ new internally coated tbg w/ pkr
9. Circ. packer fluid
10. Run Integrity Test
11. Place well on injection

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

HAYLIE URIAS

Title OPERATION TECH

Signature

Haylie Urias

Date

07/10/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/S/ ALEXIS C. SWOBODA

PETROLEUM ENGINEER

Date

JUL 12 2007

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GWW