Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED

OMB NO	1004-0135
Expires Janu	ary 31 2004

SUNDRY NOTICES	AND	REPORTS	ON	WELLS
----------------	-----	---------	----	-------

5 Lease Serial No LC-030174-A

	or proposals to drill or to re-enter an form 3160-3 (APD) for such proposals.	6 If Indian, Allottee or Tribe Name
	- Other instructions on reverse side	7 If Unit or CA/Agreement, Name and/or No NM 71022A
Fype of Well Oil Well X Gas Well Other Name of Operator		8 Well Name and No RHODES FEDERAL #222 UNIT
CIMAREX ENERGY COMPANY ATTN: ZE a Address	ENO FARRIS	9 API Well No
_P.OBOX 140907, IRVING, TEXAS 75	3b Phone No. (<i>include area co.</i>	30-025-12034
Location of Well (Footage, Sec. T, R M., or Survey		10 Field and Pool, or Exploratory Area
UNIT LETTER J, 1650' FSL & 1650' E		RHODES-YATES-7 RIVERS GAS
SEC.22, TWP.26S, RGE.37E	: 1911	11 County or Parish, State
		·
12 CHECK APPROPRIAT	E BOX(ES) TO INDICATE NATURE OF NOT	
TYPE OF SUBMISSION		FACTION
		(.091011;
Notice of Intent	Acidize Deepen	rioduction (stat/Resume) A.B. Water Shiil-Off
	Alter Casing Fracture Treat	Reclamation Willintegrity
X Subsequent Report	Casing Repair New Construction	Recomplete S & Orfer
П.	Change Plans X Plug and Abandon	Recomplete OF Temporarily Abandon
I mal Abandonment Notice		
	Convert to Injection Plug Back	Water Disposal
	Notices shall be filed only after all requirements, including	
testing has been completed. Final Abandonment determined that the final site is ready for final insp. 06/06/07: TAG EXISTING CIBP @ 2, & TAG TOP OF CMT. PLUC	Notices shall be filed only after all requirements, including section.) 1. Notices shall be filed only after all requirements, including section.) 1. Notices shall be filed only after all requirements, including section.)	
testing has been completed. Final Abandonment determined that the final site is ready for final insp. 06/06/07: TAG EXISTING CIBP @ 2, & TAG TOP OF CMT. PLUC	Notices shall be filed only after all requirements, including bection) ,810'; CIRC. WELL W/ PXA MUD; MIX & PUNG @ 2,621'. CMT. PLUG @ 1200'; WOC & PRES. TEST CN	TP A 40 SX. CMT. PLUG @ 2,810; WCC
testing has been completed. Final Abandonment determined that the final site is ready for final inspection of the final site is ready for final inspection. O6/06/07: TAG EXISTING CIBP @ 2, & TAG TOP OF OMT. PLUG 06/07/07: PERF. & SQZ. A 60 SX. TOP OF OMT. PLUG @ 1,0	Notices shall be filed only after all requirements, including section.) ,810'; CIRC. WELL W/ PXA MUD; MIX & PUNG @ 2,621'. CMT. PLUG @ 1200'; WCC & PRES. TEST CNO35';	T. PLUG TO 1,500# - HELD OK; TAG
testing has been completed. Final Abandonment determined that the final site is ready for final inspection of the final site is ready for final inspection. TAG EXISTING CIBP @ 2, & TAG TOP OF OMT. PLUG 06/07/07: PERF. & SQZ. A 60 SX. TOP OF OMT. PLUG @ 1,006/08/07: PERF. & SQZ. A 115 SX.	Notices shall be filed only after all requirements, including bection) ,810'; CIRC. WELL W/ PXA MUD; MIX & PUNG @ 2,621'. CMT. PLUG @ 1200'; WOC & PRES. TEST CN	AP A 40 SX. CMT. PLUG @ 2,810; WCC AT. PLUG TO 1,500# - HELD OK; TAG @ 305; TO SURFACE.
testing has been completed. Final Abandonment determined that the final site is ready for final inspection of the final site is ready for final inspection. TAG EXISTING CIBP @ 2, & TAG TOP OF OMT. PLUG @ 1,000 OF OMT. PLUG @ 1,000 OF OMT. PLUG @ 1,000 O6/08/07: PERF. & SQZ. A 115 SX.	Notices shall be filed only after all requirements, including the filed only after all requirements and all all all all all all all all all al	AP A 40 SX. CMT. PLUG @ 2,810; WOC AT. PLUG TO 1,500# - HELD OK; TAG @ 305; TO SURFACE. ASING & WELD ON DRY HOLE MARKER.
testing has been completed. Final Abandonment determined that the final site is ready for final inspection of the final site is ready for final inspection. TAG EXISTING CIBP @ 2, & TAG TOP OF CMT. PLUG @ 1,000 OF CMT.	Notices shall be filed only after all requirements, including the filed only after all requirements and all all all all all all all all all al	AP A 40 SX. CMT. PLUG @ 2,810; WOC AT. PLUG TO 1,500# - HELD OK; TAG @ 305; TO SURFACE. ASING & WELD ON DRY HOLE MARKER.
testing has been completed. Final Abandonment determined that the final site is ready for final inspection of the final site is ready for final inspection. O6/06/07: TAG EXISTING CIBP @ 2, & TAG TOP OF OMT. PLUG @ 2, & TAG TOP OF OMT. PLUG @ 1,0 O6/08/07: PERF. & SQZ. A 115 SX. DIG OUT & CUT OFF WELL	Notices shall be filed only after all requirements, including the filed only after all requirements and all all all all all all all all all al	AP A 40 SX. CMT. PLUG @ 2,810; WCC AT. PLUG TO 1,500# - HELD OK; TAG @ 305; TO SURFACE.
testing has been completed. Final Abandonment determined that the final site is ready for final inspection of the final site is ready for final inspection. 06/06/07: TAG EXISTING CIBP @ 2, & TAG TOP OF CMT. PLUC 06/07/07: PERF. & SQZ. A 60 SX. TOP OF CMT. PLUC @ 1,0 06/08/07: PERF. & SQZ. A 115 SX. DIG OUT & CUT OFF WELL WELL PLUCGED AND ABANDONED 06/08	Notices shall be filed only after all requirements, including bection) ,810'; CIRC. WELL W/ PXA MUD; MIX & PUNG @ 2,621'. CMT. PLUG @ 1200'; WOC & PRES. TEST ON 035'; CMT. PLUG INSIDE & OUT OF 7-5/8" CSG. CHEAD 3' B.G.L.; WELD STEEL PLATE ON CAB.	ACCEPTED FOR RECORD JUL 18 2007
testing has been completed. Final Abandonment determined that the final site is ready for final inspection of the final site is ready for final inspection. 06/06/07: TAG EXISTING CIBP @ 2, & TAG TOP OF CMT. PLUG @ 1,000 OF CMT. PLUG @ 1,00	Notices shall be filed only after all requirements, including nection.) ### REST ONLY ### REST	ACCEPTED FOR RECOR
testing has been completed. Final Abandonment determined that the final site is ready for final inspection of the final site is ready for final inspection. 06/06/07: TAG EXISTING CIBP @ 2, & TAG TOP OF CMT. PLUC @ 1,000 OF CMT. PLUC @ 1,00	Notices shall be filed only after all requirements, including bection) ,810'; CIRC. WELL W/ PXA MUD; MIX & PUNG @ 2,621'. CMT. PLUG @ 1200'; WOC & PRES. TEST ON 035'; CMT. PLUG INSIDE & OUT OF 7-5/8" CSG. CHEAD 3' B.G.L.; WELD STEEL PLATE ON CAB.	JUL 18 2007 BURZAU OF LAND MANAGEMENT
testing has been completed. Final Abandonment determined that the final site is ready for final inspection of the final site is ready for final inspection. 06/06/07: TAG EXISTING CIBP @ 2, & TAG TOP OF CMT. PLUG @ 1,000 OF CMT. PLUG @ 1,00	Notices shall be filed only after all requirements, including nection.) ### REST ONLY ### REST	JUL 18 2007 BURZAU OF LAND MANAGEMENT
testing has been completed. Final Abandonment determined that the final site is ready for final inspection of the final site is ready for final inspection. 06/06/07: TAG EXISTING CIBP @ 2, & TAG TOP OF CMT. PLUG 06/07/07: PERF. & SQZ. A 60 SX. TOP OF CMT. PLUG @ 1, C 06/08/07: PERF. & SQZ. A 115 SX. DIG OUT & CUT OFF WELL WELL PLUGGED AND ABANDONED 06/08 WELL PLUGGED AND ABANDONED 06/08 Thereby certify that the foregoing is true and correct Name (Printed/Typed) DAVID A. EYLER	Notices shall be filed only after all requirements, including nection.) (810'; CIRC. WELL W/ PXA MUD; MIX & PUNG @ 2,621'. CMT. PLUG @ 1200'; WOC & PRES. TEST ON 035'; CMT. PLUG INSIDE & OUT OF 7-5/8" CSG. CHEAD 3' B.G.L.; WELD STEEL PLATE ON CASS/07.	JUL 1 8 2007 BURYAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

Fitle 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction