

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

SWD

2. Name of Operator

SOUTHWEST ROYALTIES, INC.

3a. Address

6 Desta Drive, Suite 2100, Midland, TX 79705

3b. Phone No. (include area code)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FNL & 660' FEL, SEC. 34, T 17 S, R 33E, UNIT A

5. Lease Serial No.

NM 94189

If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

ELLIAMS 34 FED.

12

9. API Well No.

30 025 33894 33094

10. Field and Pool, or Exploratory Area

MALJAMAR

11. County or Parish, State

LEA COUNTY

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

6-25-07 M.I.R.U. Basic Energy Services P & A Rig #1273. P.O.O.H. w/134 jots. of 2 7/8" duolined tbq. & pkr. 6-26-07 Finish pulling tbq. Set 5 1/2" C.I.B.P. @4,197'. Circulate 10# M.L.F. w/35 sx. cmt. T.O.C. circulated @3,843'. Pull out of hole w/tbq. N.D. B.O.P. & wellhead. Screw on P.N. Remove 5 1/2" csg. slips. Csg. shows free @1,900'. Rig up W.L. & cut csg. @2,600'. Try to pull csg. Not free. R.U. pump & pressure up to 800#. Csg. holding good. No leaks. Bleed off pressure & remove P.N. N.U. B.O.P. & go in hole w/tbq. to 2,640' & mix & spot 25 sx. cmt. W.O.C. & tag 2,558'. Marlon Deaton, N.M.B.L.M. & Buddy Hill, H.M. O.C.D., o.k. w/tag @2,558'. Cut & pull csg. from 1,515'.

6-28-07 T.F.H. w/tbq. to 1,572'. Mix & spot 60 sx cmt. W.O.C. & tag @1,358'. T.I.H. to 398' & spot 40 sx. cmt. W.O.C. & tag @260'. Pull up to 60'. Spot 20 sx. cmt. to surface. Cut well & install Dryhole Marker

ACCEPTED FOR RECORD

JUL 28 2007

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

RANDALL MINEAR

Title

P & A SUPV.

Signature

Date 7-3-07

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Ray W. Wink

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GW