Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-005-20728
1301 W. Grand Ave, Artesia, NM 88210			5. Indicate Type of Lease
Onstruct III 1220 South St. Francis Dr.		STATE FEE	
District IV Santa Fe, INM 87303		6. State Oil & Gas Lease No.	
1220 S St Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name: Booher 35			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Booner 35
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well No. 1
2. Name of Operator			9. OGRID Number
John R. Stearns dba Stearns			21566
3. Address of Operator			10. Pool name or Wildcat
HC 65, Box 988, Crossroads, NM 88114			Tom Tom (San Andres)
4. Well Location			
Unit Letter D : 467 feet from the FNL line and 467 feet from the FWL line Section 35 Township 7S Range 31E NMPM County Chaves			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application or Closure			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐			
TEMPORARILY ABANDON			
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING/CEMENT	TJOB 📙
	COMPLETION		
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of			
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
recompletion. Propose P&A 8 5/8 @ 1650	725 sx. Circulated		
4 1/2 @ 4150 250 sx. 3200 TOC			
1. CIBP @ 3950. Circulate hole with mud laiden fluid. Set 25 sx cmt on top BP.			
	@ 2900. Sqz. 40 sx. cmt. WOC &		S. S
	@ 1450. Displace to 1600. WOC &	Tag	Sel of the second of the secon
4. Perf. csg. @ 350. Circulate cement to surface (40 sx) 5. Cut off Wellhead and Install Dry Hole Marker.			
S Rocalities V			
			S HOUD S
THE OIL CONSERV	ATION DIVISION MUST		1010 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
BE NOTIFIED 24 HOURS PRIOR TO THE			
BEGINNING OF PLUGGING OPERATIONS.			
BEGINNING OF PLO	Jadilla of Litations:		
I hereby certify that the information a	have is true and complete to the best of n	y knowledge and beli	ief. I further certify that any pit or below-grade tank
has been/will be construyed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
			—
SIGNATURE SECULT-	TITLE A	Agnet	DATE <u>7/26/07</u>
Time or maint name Posser Propoles			
Type or print name Roger Brooks E-mail address: Telephone No. 432-580-7161			
111 3 1 2007			
APPROVED BY	W-Wints TITLE		DATEJUL 3 1 2007
Conditions of Approval (if any):	1		Forms On-A-Disk - (214) 340-9429 - FormsOnADisk com

Form provided by Forms On-A-Disk · (214) 340-9429 · FormsOnADisk.com