.. Form 3!.60-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR OCD-HOBBS BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No 1004-0137 Expires. July 31, 2010

5. Lease Serial No. NM 62602

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well.	Use Form 3160-3 (APD) for suc	ch proposals.		
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/Agreem	ent, Name and/or No
Type of Well Oil Well Gas W		8. Well Name and No HAMON A FED COM #1		
2 Name of Operator LEGACY RESERVES OPERATING LP			9 API Well No. 30-025-30881	
3a Address P O BOX 10848 MIDLAND, TX 79702	(include area code) -5200	10. Field and Pool or Exploratory Area TEAS; BONE SPRING, EAST		
4 Location of Well (Footage, Sec., T,R,M., or Survey Description) 1650 FSL 1980 FEL UNIT LETTER J SEC 7 T20S R34E			11. Country or Parish, State LEA, NM	
12. CHEC	CK THE APPROPRIATE BOX(ES) TO IND	DICATE NATURE OF NO	TICE, REPORT OR OTHER	DATA
TYPE OF SUBMISSION		TYPE OF A	CTION	
Notice of Intent		ture Treat R	roduction (Start/Resume) eclamation ecomplete	Water Shut-Off Well Integrity Other
Subsequent Report	☐ Change Plans ☐ Plug	and Abandon T	emporarily Abandon	
Final Abandonment Notice	Convert to Injection Plug peration Clearly state all pertinent details, i		/ater Disposal	
following completion of the involtesting has been completed. Final determined that the site is ready for SEE ATTACHED	Received ANG 2007 ANG 200 ANG	ter all requirements, includ	ACCEPTED AUG BUREAU OF L	FOR RECORD 1 0 2007 AND MANAGEMENT D FIELD OFFICE
Name (Printed/Typed) D. PATRICK DARDEN	Title PETROLEUM ENGINEER, P.E.			
Signature R. Fabrile	Pard	Date 08/07/2007		
	THIS SPACE FOR FED	ERAL OR STATE (OFFICE USE	
that the applicant holds legal or equitable entitle the applicant to conduct operation		vould Office		ate
Title 18 U S C Section 1001 and Title 4 fictitious or fraudulent statements or rep	3 U.S.C. Section 1212, make it a crime for any resentations as to any matter within its jurisdictions.	person knowingly and willfu	lly to make to any department	or agency of the United States any false,

(Instructions on page 2)



Actual Plugging Procedure on the Hamon "A" Fed Com #1

7/25/07	Set CIBP @ 6,350'. Dump 35' cmt on top of plug.
7/26/07	Run freepoint, cut 5-1/2" prod csg @ 5,700'.
7/27/07	POH LD 142 jts 5-1/2" csg.
7/30/07	Circ well w/200 bbls 9# mud.
7/30/07	Spot 27sx cmt plug fr/5,774' (across 5-1/2" csg stub), tag TOC @ 5,657'. Jim McCormick w/BLM approved plug.
7/30/07	Spot 40sx cmt plug fr/5,280' (across 8-5/8" shoe). SDFN.
7/31/07	Tag TOC @ 5,156'. Jim McCormick W/BLM approved plug.
7/31/07	Spot 48sx cmt plug fr/3,967' (across DVT). WOC 4 hrs. Tag TOC @ 3,780'. BLM rep on location approved plug.
7/31/07	Spot 46sx cmt plug fr/3,270' to 3,230' (across base of salt section). BLM rep on location called plug good.
7/31/07	Spot 32sx cmt plug fr/1,550' to 1,430' (across top of salt section).
7/31/07	Spot 30sx cmt plug fr/486' (across surf csg shoe). SDFN.
8/01/07	Tag TOC @ 312'.
8/01/07	Spot 21sx plug fr/74' to surf.
8/01/07	Filled 8-5/8" csg to surf.
8/01/07	BLM rep said plugging job was good.
8/01/07	Capped well & installed P&A marker w/Operators name: Legacy Reserves, LP, Lease Serial number: NM62602, Location: Qtr – Qtr section (NWSE7), Section (7), Township (T20S) & Range (R34E). Job approved by Jim McCormick w/BLM (505-631-4547).
8/01/07	Dug up safety anchors, covered hole and cleaned location
Note:	Will send subsequent Sundry Notice when location is restored.