Submit 3 Copies To Appropriate District Office	State of New Me		Form C-103
District I 1625 N. French Dr , Hobbs, NM 88240	Energy, Minerals and Nati	iral Resources	May 27, 2004 WELL API NO.
District II 1301 W Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-05244
District III	1220 South St. Fran		5. Indicate Type of Lease STATE FEE □
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u>	Santa Fe, NM 8'	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			E-2344
	CATION FOR PERMIT" (FORM C:101) FO	UG BACK TO A	7. Lease Name or Unit Agreement Name State "A"
1. Type of Well: Oil Well	Gas Well Other Other	00	8. Well Number 1
2. Name of Operator	W. Allon	3000 0	9. OGRID Number 236378
Saber Resources, LLC. 3. Address of Operator	S SIE	1119 E	10. Pool name or Wildcat
400 W. Illinois, Suite 950, Midlan	id, TX 79701 \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\		Denton - Devonian
4. Well Location	165	\$.G.	
	1980' feet from the South Township 15S	shalf and	660'feet from theWestline
Section 2	Township 15S 11. Elevation (Show whether DR		NMPM Lea County
	3820' DF	, Mid, KI, GR, eic.)	
Pit or Below-grade Tank Application O			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mil	Below-Grade Tank: Volume		nstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	SUBS REMEDIAL WORK COMMENCE DRII CASING/CEMENT	LLING OPNS. P AND A
OTUED:	П	OTHER: Temporal	rily Abandon
OTHER: 13. Describe proposed or compl	leted operations. (Clearly state all		I give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
tbg and set @ 11,785'. Pumped plug 11,785'. RIH with CIBP on wireline	mud from 11,785' to 9000'. RUV and set @ 9030'. RIH with bailer 520 psi for 30 minutes (notified Gad.	WL – RIH with baile and dump bail 2 sxs ary Wink w/NMODO	th gauge ring to 11,800'. RIH with CIBP on er and dump bail 2 sxs cmt on CIBP @ s cmt on CIBP. ND BOP, NU WH. RU pump C prior to running test). Shut well in.
	This Approval of Abandonment E	Temporary - xpires	7/27/12
Y 1 1			11:1:0
			e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan .
signature //w////	TITLE_	VP - Operations	DATE_ 8 /16/07
Type or print name Doug Keathley For State Use Only	E-mail address: doug@s		Telephone No. 432-685-0169
APPROVED BY: (auglice Conditions of Approval (if any))	I wink) REPRESENTATIVE	ENVSTAFF MANAGER DATE

AUG 1 6 2007

