Form 3160-5 (April 2004)

GWW

## UNITED STATES DEPARTMENT OF THE INTERIOR OCD HOBBS

## BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OM B No 1004-0137
Expires March 31, 2007

5.	Lease Scrial No
	NM 35612

6.	If Ind	ian,	A	llottee o	r Tribe	Name

abandoned we	ell. Use Form 3160 - 3 (/	APD) for si	uch pro	posals.				
SUBMIT IN TR	IPLICATE- Other instr	ructions or	rever	se side.		7. If Unit or	CA/Agreement, Name and/or No.	
1. Type of Well Gas Well Other						8. Well Name and No.		
2. Name of Operator Ray Westall							Polewski Federal #2  9. API Well No	
				o. (include area code) 1370			30-025-35340  10. Field and Pool, or Exploratory Area	
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)						Lusk De	elaware, West	
990' FNL & 1658' FWL Sec. 31 T19S-R32E						-	or Parish, State unty, New Mexico	
12. CHECK AI	PPROPRIATE BOX(ES) TO	INDICATE	NATUR	E OF NOTIO	CE, RE	EPORT, OR	OTHER DATA	
TYPE OF SUBMISSION			TYP	E OF ACTION	ON .			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Tr New Consi  Plug and A Plug Back	truction	Reclama	ation lete arily Aba	t/Resume) andon	Water Shut-Off Well Integrity Other	
Attach the Bond under which the following completion of the invitesting has been completed. Fit determined that the site is ready.  Set CIPB @ 5100' above E spot 100' cmt plug 4285-43 spot 100' cmt plug 3942-40 spot 100' cmt plug 2602-27 spot 100' cmt plug 794-894 spot 10 sxs surface plug	ectionally or recomplete horizontally the work will be performed or provided operations. If the operation and Abandonment Notices shall be a for final inspection.)  Delaware perfs 5145-7202 spot 385. Top Delaware sands 433542. 8 5/8" csng @ 3992.  Top Yates 2652. 13 3/8" csng @ 844	y, give subsurfar de the Bond No results in a mult filed only after a 25 sxs plug or	ce location on file w iple compl ill requirer	s and measured outh BLM/BIA etion or recomp	d and true Require pletion in g reclama	e vertical depths d subsequent re a new interval ation, have beer	s of all pertinent markers and zones. eports shall be filed within 30 days , a Form 3160-4 shall be filed once	
14. I hereby certify that the fore Name (Printed/Typod) Randall Harris	going is true and correct		Title G	eologist				
Signature	160		Date		08	3/08/2007		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE OVED								
Approved by  Conditions of approval, if any, are a certify that the applicant holds legal which would entitle the applicant to	or equitable title to those rights in conduct operations thereon.	the subject lea	t or ise Oi	tle Tice		AUG	ate 1 6 2007	
States any false, fictitious or fraudule	ent statements or representations a	as to any matter	person kno within its	owingly and w jurisdiction	Tilfully to	make to any	department of the United RICK ENGINEER the United	
(Instructions on page 2)						PETROLE	UIVI	

## **SUNDRY NOTICE SPECIAL STIPULATIONS**

- 1. Approval is granted to plug this well with the following modifications to the proposed plugging procedure.
- 2. All plugs below the surface plug must be at least 25 sacks of cement and 100' plus an additional 10% for each 1000 feet of depth.
- 3. The plug proposed for 2702' should be moved to 3420' and be at least 25 sacks of cement for the Base of the Salt.
- 4. The plugs @ 5100', 4042' and 894' must be tagged.

Plugging procedures must conform to 43 CFR 3162.6.d and Onshore Order No. 2.III.G or NMOCD orders if they are more stringent.

## ALL OF THE WORK AUTHORIZED HERE MUST BE COMPLETED WITHIN 90 DAYS.

Engineering can be reached at 505-706-2779 for any variances that might be necessary.

F Wright 8/16/07

e. 1923