| OCD-HOBBS | -HOBBS |
|-----------|--------|
|-----------|--------|

| 1. Type of Well | CATE- Other instructions on reverse s | als. | | |
|--|--|--|--|--|
| 3a. Address | 3a Address 3b Phone No (include area code) | | | |
| | 509 Market St., Suite 300, Shreveport, LA 71101 318-221-6156 4 Location of Well (Footage, Sec., T, R, M, or Survey Description) | | | |
| Surface: 300 FNL & 1650' FEL | | | | |
| 12. CHECK APPRO | PRIATE BOX(ES) TO INDICATE NATURE O | F NOTICE, REPORT, OR OTHER DATA | | |
| TYPE OF SUBMISSION | TYPE OI | FACTION | | |
| Notice of Intent Subsequent Report Final Abandonment Notice | Acudize Deepen Alter Casing Fracture Treat Casing Repair New Construction Change Plans Plug and Abandon Convert to Injection Plug Back | Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Recomplete Other Temporarily Abandon intermediate casing. Water Disposal Image: Contemplete casing. | | |
| If the proposal is to deepen directional Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abi determined that the site is ready for fir 11-3/4", H40A, 42#, PPF 8RD cs 8-5/8", J55, 32#, 8RD, ST&C cs C 4/10% FL-62. Cement plug above and below i Top salt 1420' Top cement plug Cement plug above and below 60' cement plug to surface. | lly or recomplete horizontally, give subsurface locations and k will be performed or provide the Bond No on file with Bl operations. If the operation results in a multiple completion andonment Notices shall be filed only after all requirements, ial inspection) sg @ 1425', 4 centralizers. Lead w/1175 sx CF +4% g. @5999', 6 centralizers. Lead w/2540 sx. 35:65 PC intermediate casing shoe @ 5999' - 50' in - 50' out. 1370'. Cement plug below base salt @ 2694'. surface casing shoe at 1425' - 50' in 50' out. | starting date of any proposed work and approximate duration thereof measured and true vertical depths of all pertinent markers and zones LM/BIA. Required subsequent reports shall be filed within 30 days or recompletion in a new interval, a Form 3160-4 shall be filed once including reclamation, have been completed, and the operator has Gel; tail w/400 sx. c+2% CACL - cement to surface. DZ C 6% GEL + 5# LCM-1 +#/10% FL-FL-52; tail w/450 sx. | | |
| Signature | RI Wise Title | 29. Agent | | |
| | THIS SPACE FOR FEDERAL OR STATE OFFICE USEFOR THE | | | |
| Approved by Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu | Title d Approval of this notice does not warrant or pitable title to those rights in the subject lease office ct operations thereon | ACCEPTED ate 2001 AUG 2 2 2001 AUG 2 2 2001 | | |
| Title 18 U.S.C. Section 1001 and Title 43 U.S. States any false, fictutious or fraudulent state (Instructions on page 2) | S.C. Section 1212, make it a crime for any person knowing tements or representations as to any matter within its jurise | ly and willfully to make to any department of agents lot the United diction | | |

. ۲. کرچ

SUNDRY NOTICE SPECIAL STIPULATIONS

- 1. Approval is granted to plug this well with the following modifications to the proposed plugging procedure.
- 2. The plug proposed for 5999' must be moved to 6049' and must be at least 160'.
- 3. Add a 130' plug @ 3000'.

÷ ,;;

- 4. A 130' plug should be spotted @ 2744' for the Base of the Salt.
- 5. A 120' plug should be spotted @ 1475' for the Top of the Salt and the surface casing shoe..
- 6. All of the proposed plugs other than the surface plug can be eliminated.
- 7. The plugs @ 6049', 2744' and 1475' must be tagged.

***All plugs below the surface plug must be at least 100' and 25 sacks of cement plus an additional 10% for each 1000 feet of depth.

Plugging procedures must conform to 43 CFR 3162.6.d and Onshore Order No. 2.III.G or NMOCD orders if they are more stringent.

ALL OF THE WORK AUTHORIZED HERE MUST BE COMPLETED WITHIN 90 DAYS.

<u>Engineering</u> can be reached at 505-706-2779 for any variances that might be necessary.

F Wright 7/31/07