State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION WELL API NO 1220 South St. Francis Dr. 1625 N French Dr , Hobbs, NM 88240 30-025-35385 Santa Fe, NM 87505 5 Indicate Type of Lease DISTRICT II 1301 W Grand Ave, Artesia, NM 88210 STATE FEE X DISTRICT III 6 State Oil & Gas Lease No 1000 Rio Brazos Rd, Aztec, NM 87410 7 Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A North Hobbs (G/SA) Unit DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form G101) for such proposals) Section 32 8 Well No 1 Type of Well 913 Oil Well X Gas Well Other 2 Name of Operator 9 OGRID No 157984 Occidental Permian Ltd. 3 Address of Operator 10 Pool name or Wildcat Hobbs (G/SA) HCR 1 Box 90 Denver City, TX 79323 4 Well Location Unit Letter L Feet From The Feet From The West Line 1860 South 1245 Township 18-S NMPM County Section Range 38-E 11 Elevation (Show whether DF, RKB, RT GR, etc.) 3643 (12'KB) Pit or Below-grade Tank Application or Closure Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness Below-Grade Tank: Volume bbls; Construction Material Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. **PLUG & ABANDONMENT** PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB X OTHER! OTHER: Squeeze gas flow 13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU. Kill well POOH w/production equipment. 2. Clean out to PBTD @4285'. 3. Run CNL/CCL/GR log. 4. Locate leak. Squeeze. 5. Clean out to PBTD. 6. Run back in hole w/production equipment. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Ifurther certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines or an (attached) alternative OCD-approved , a general permit SIGNATURE TITLE Administrative Associate 08/27/2007 TYPE OR PRINT NAME Mendy bhnson E-mail address: mendy_johnson@oxy.com TELEPHONE NO 806-592-6280 For State Use Only AUG 28 2007 Jans APPROVED BY

CONDITIONS OF APPROVAL (7) ANY