State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
DISTRICT I 1625 N French Dr , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO 30-025-35554	
<u>DISTRICT II</u>	,		5 Indicate Type of Lease	
1301 W Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III			6 State Oil & Gas Lease No	
1000 Rio Brazos Rd, Aztec, NM 87410			7 Lease Name of Unit Agreen	aant Nama
SUNDRY NOTICES AND REPORTS ON WELLS			7 Lease Name or Unit Agreem	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)			South Hobbs (G/SA) Unit Section 4	
1 Type of Well			8 Well No 245	
Oil Well Gas Well Other Temporarily Abandoned			213	
2 Name of Operator Occidental Permian Ltd.			9 OGRID No 157984	
3 Address of Operator			10 Pool name or Wildcat	Hobbs (G/SA)
HCR I Box 90 Denver City, TX	79323			
4 Well Location	Feet From The South	709 Fee	et From The East	Line
Unit Letter P 1303		700		Lea County
Section 4	Township 19-S 11 Elevation (Show whether DF, RK 3610' GL		S NATION	Lea County
			Valuatudes (17. 2) in analysis	<u>) </u>
Pit or Below-grade Tank Application or Closure Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
	Appropriate Box to Indicate Na	ture of Notice Report or (Other Data	
NOTICE OF INTE		SUBS	SEQUENT REPORT O	F:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	G CASING
TEMPORARILY ABANDON	CHANGE PLANS	NS PLUG & ABANDONMENT		
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	NT JOB	324250
OTHER Repair casing leak	X	OTHER:	23222	32425262
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. Pull equipment.				
2. Locate leak.			15 6	
3 Perform repairs as required4. Notify NMOCD of pressure test.			14	, c \(\dagger\)
2. Locate teak. 3. Perform repairs as required 4. Notify NMOCD of pressure test. 5. Run equipment.				
			41	01681
		11 1 5 15 11	al at a second a toul	has been/will be
I hereby certify that the information above is constructed or	true and complete to the best of my know	ledge and belief. Hurther certify	that any pit or below-grade tank	nas been/will be
closed according to NMOCD guidelines	, a general permit	or an (attached) alternativ	e OCD-approved	
SIGNATURE Mendy	ahman	TITLE Administrative	Associate DAT	E 08/27/2007
TYPE OR PRINT NAME Mendy A. Jo		mendy_johnson@oxy.com		806-592-6280
For State Use Only	J. J. J. J. C. Pis	LO REPRESENTATIVE (VSTAFF MANAGEM	AUG 2 8 2007
APPROVED BY	my	TITLE	DA DA	ГЕ
CONDITIONS OF APPROVAL/IF ANY				