ē	Submit 3 Copies To Appropriate District Office		New Me			Form Revised June	C-103
	District I	Energy, Minerals	and Natu	ral Resources	WELL API NO.	Revised Julic	10, 2003
r	1625 N. French Dr., Hobbs, NM 88240 District II	OH COMEEN		DIVICION	30-025-36244		
	1301 W. Grand Ave, Artesia, NM 88210	OIL CONSER			5. Indicate Type	of Lease	
	District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 Sout			STATE	FEE 🗌	
	District IV	Santa F	e, NM 87	7505	6. State Oil & G	as Lease No.	
	1220 S St. Francis Dr., Santa Fe, NM						-
	87505 SUNDRY NOTI	CES AND REPORTS O	N WELLS		7. Lease Name of	or Unit Agreement	Name
	(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEE	EPEN OR PLU	JG BACK TO A	LITTLE KING		
	DIFFERENT RESERVOIR USE "APPLIC	ATION FOR PERMIT" (FOR	RM C-101) FC	OR SUCH			
	PROPOSALS.) 1. Type of Well:				8. Well Number	•	
	Oil Well Gas Well	Other			2		
	2. Name of Operator				9. OGRID Num	ber	
	Devon Energy Production Company	y, LP			6137		
	3. Address of Operator				10. Pool name o	r Wildcat	
	20 North Broadway, Suite 1500, Ol	klahoma City, Oklahoma	a 73102		SAN SIMON; Y	ATES	
	4. Well Location						
					6.101	.1 ***	1.
	Unit LetterL_:_171	0'feet from the	_South	line and	640'feet from	theWest	_line
	Section 9	Township 228	C Dor	nge 35E	Lea	County	
	Section 9	11. Elevation (Show w				County	
		3557 GL	meiner DR,	, KKD, KI, OK, etc	.)		in commence
	12 Check A	ppropriate Box to In	ndicate N	ature of Notice	Report or Other	r Data	CONTRACTOR CONTRACTOR
	NOTICE OF IN		ilaicate iv		SEQUENT RE		
	PERFORM REMEDIAL WORK	PLUG AND ABANDO	N 🖾	REMEDIAL WOR		ALTERING CAS	ING 🗆
	FERI ONWINCIMEDIAL WORK	I LOO AND ADANDON	• 🖂	TEINEDINE WOT		ALTERNIO OAO	
	TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	RILLING OPNS.	PLUG AND ABANDONMEN	
	PULL OR ALTER CASING	MULTIPLE		CASING TEST A	ND 🗆	ADAM DE MINICA	723856
	TOLE SICKLE LIKE SHOWS	COMPLETION		CEMENT JOB			87
			_		/,	AUG 2007	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	OTHER:			OTHER:	(3	AIIG 2007	· □~\
	13. Describe proposed or comp	leted operations. (Clear)	ly state all p	pertinent details, ar	nd give pertinent de	es, including estin	hated date
	of starting any proposed wo	rk). SEE RULE 1103.	For Multip	le Completions: A	ttach wellbore diag	ram of proposecoc	ompleti o n/
	or recompletion.				\	5 000	N/
						120×	Mey/
	1. MIRU. POOH w/ 2-3/8" tubing a	and rod string Dump 35	5' cement o	n top of evist CIRI	P @ 4030' (Seven)	River perfs old 1	41417)
	2. Set CIBP at 3966'. Dump 35' cen	nent on top (Yates Perfs	3986'-	3996')	(W 4030 . (Seven)	idver peris-w_309.) 4141 <i>j</i> .
	3. Circulate wellbore with 9.5 ppg s			<i>3,</i> 7,0).			
	4 Cut 5-1/2" casing at +/-1725' PC	OH w/casing. Spot 30.5	Sx (148') s	tub plug at 1775'.	(Calc. TOC at 1627	7'). WOC & Tag.	
	5. Spot 40 Sx (150') plug at 1350'. (6. Circulate 30 Sx plug from 110' to	(Calc. TOC at 1200'). (8	8-5/8" shoe	@ 13002)_WQG	PRISERVAT	ION DIVIDIO	F-10-7
	o. Chediate 30 3x plug from 110 to	surface.					
	7. Cut wellhead off 3' below ground	d level. Set dry hole ma	rker.		IFIED 24 HOU		
	8. Clean & restore location.			BEGINNI	ng of Plug	GING OPERA	TIONS.
	I hereby certify that the information	shave is true and same	oto to the L	act of my lenovylad	go and haliaf		
			eie io ille D	est of my knowled;	ge and belief.		
	SIGNATURE KAMIE SI	W/ TIT	LE: Engi	neering Techniciar	n DAT	ΓE 8/27/07	
	1 1000 xx						
	Type or print name Ronnie Slack	E-mail address:	Ronnie.Sl	lack@dvn.com	Telephone	No. 405-552-4615	
	(This space for State use)				-		
	\mathcal{L}	1,1-110	C HELD S	THREE-MEATINE	water remed	🐡 🖊 AUG 3 🗈	1 2637
	APPPROVED BY LONG U	1. WIMR	TITLE	······································		DATE	
	Conditions of approval, if any:						

DEVON ENERGY	PRODUCTION COMPANY LP			
Vell Name: LITTLE KINGS #2	Field: GAUCHO AREA UNASSIGNED			
ocation: 1710' FSL & 640' FWL; SEC 9-T225-R35E	County: LEA State: NM			
levation: 3557' GL	Spud Date: 4/30/03			
PI#: 30-025-36244 Prepared by: Ronnie Slack	Date: 8/23/07 Rev:			
PROPOSED P&A	9.5# Mud			
12-1/4" Hole 8-5/8", 24#, J55, ST&C, @ 1,300' Cmt'd w/650 Sx. Circulated to surface.	Proposed: 1. Spot 40 Sx (150') plug at 1350'. WOC & Tag. 2. Calc TOC at 1200'. WOC & Tag. 9.5# Mud Proposed: 1. Cut 5-1/2" csg +/- 1725'. POOH w/ casing. 2. Spot 30 Sx (148') stub Plug at 1775'. Calc TOC at 16 3. WOC & Tag.			
TOC @ 1785' (CBL-5/28/03)	9.5# Mud Proposed: 1. Circulate wellbore w/9.5 ppg mud Proposed: 1. Set CIBP @ 3966'			
<u>YATES</u> (6/6/03) 3,986' - 3,996' <u>SEVEN RIVERS</u> (5/30/03)	2. Dump 35' cement on top. PBD @ 3931' Proposed: Dump 35' cement on CIBP @ 4030'. PBD @ 3995' CIBP @ 4,030' (6/6/03)			
4,039' - 4,141' <u>CAPITAN REEF</u> (5/28/03) 4,196' - 4,251'	35' Cement. 4,150' PBD CIBP @ 4,185' (5/30/03)			

7-7/8" Hole <u>5-1/2", 15.5#, J55, LT&C, @ 4,450'</u> Cmt'd w/660 Sx TOC @ 1785' (CBL)

