

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

PRONGHORN MANAGEMENT CORPORATION

3. Address and Telephone No.

P. O. Box 1772 Hobbs, NM 88241 505-392-2495

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL & 660' FEL  
S24 - T23S - R32E

5. Lease Designation and Serial No.

LC - 063228

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Fields #1

9. API Well No.

30-025-08119

10. Field and Pool, or Exploratory Area

CRUZ DELAWARE

11. County or Parish, State

LEA

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION


- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☒ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Move in and rig up. POOH with rods and pump.
2. Swab well. Check production and fluid level.
3. Install B.O.P. POOH with tubing.
4. Rig up wireline and perforate additional Bell Canyon Ramsey Sand pay.
5. TIH with frac tubing and packer.
6. Rig up BJ. Frac well.
7. Swab and flow test well.
8. Put well on production.
9. Clean location. Rig down. Move out.



*This well has been  
P&A'd, Final abandonment  
approved 3/31/07,*

14. I hereby certify that the foregoing is true and correct

Signed

*[Signature]*

Title

President

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

7/17/07  
ACCEPTED FOR RECORD

Date

SEP 5 2007

*[Signature]*

WESLEY W. INGRAM  
PETROLEUM ENGINEER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GW