+Submit 3 Copies to Appropriate

State of New Mexico

Form C 103 Energy, Minerals and Natural Resources Department Revised 1-1-89 District Office OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs, NM S8240 WELL API NO. P.O. Box 2088 30-025-0934**₽** 5 Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE DISTRICT T11 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE •APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Well State 'A' A/C 1 2. Name of Operator 8. Well No. 3. Address of Operator 9. Pool name or Wildcat Jalmat Tansill Yates 7 Rvrs (Gas) 79240 4. Well Location North 1980 East Unit Letter _ G Feet From The Line and Feet From The Line Section 13 Township Range 36E **NMPM** County 10. Elevauon (Show whether DF, RKB. RT, GR, ctc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB Reentry & recompletion OTHER: **OTHER** 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 5/28/03 Dig out cellar, remove P&A marker, weld new 8 5/8" & 5 1/2" csg heads. 5/29/03 RU pool well service. RU ABC Services reverse unit. GIH W 4 3/4" bit & 6 3 1/5" drill collard on 2 7/8" tbbg. Tag cmt & 184' drilled hard cmt to 230', circ hole cleam. Drilled hard cmt to 760', fell through, circulated down to 821'POOH. GIH W/ 5 1/2" csg scraper tag cmt @ 873'. Drilled out 5' of cmt, tag cmt @ 958', POOH W/ tub & scraper. GIH W 4 3/4" bit drilled out cmt stringer to 1424', ran bit to 3402'. circ hole clean, POOH. GIH W/ 5 1/2" csg scraper to 3402', displace hole W/ 2% KCL water, POOH. Released reverse uit. 6/7/03 RU P&M wireline Service. Perf Yates/Seven Rivers W/ 1 SPF @ 3021', 3028', 3034', 3043', 3056', 3063', 3073', 3082', 3116', 3122', 3128', 3135', 3148', 3164', 3168', 3214', 3264', 3274', 3326' & 3338' for a total of 20 holes. Acidize perfs from 3021' - 3338' W/ 1500 Gal. 15% HCL acid. POOH. GIH W/ 5 1/2" Model R Pkr set @ 2943', loaded annulus W/ 26 bbls 2% KCL water. Frac Yates/7 Ryrs W/ 51,000 gal WF140 foamed to 65 quality W/ 303 Tons CO2 and 50,000# 20/40 and 227,700# 12/20 Brady sand. GIH W/ 2 3/8" tbg tagged sand fill @ 3338', POOH. GIH W BP & 2 3/8" tbg set @ 3118' and BP set @ 3149'. GIH W/2" X 1 1/2" X12' RWTC pume and rods. Set 80 Parkersburg pumpjack RD on 6/21/03. Placed well on production on 6/22/03. Test Dated 7/6/03: 0 bbl/Oil; 1 bbl/water; 43 MCF 12. I hereby certify that the information above is true and complete to the best of my knowledge and helief.

(this space for State Use)

PETROLEUM ENGINEER

Agent For Raptor Resources

TELEPHONE NO. 915-697-1609

7/28/03

TYPE OR PRINT NAME Bill R. Keathly