State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 5-27-2004

FILE IN TRIPLICATE **OIL CONSERVATION DIVISION** WELL API NO DISTRICT I 1220 South St. Francis Dr. 1625 N French Dr , Hobbs, NM 88240 30-25-28334 Santa Fe, NM 87505 5 Indicate Type of Lease DISTRICT II STATE X FEE 1301 W Grand Ave, Artesia, NM 88210 6 State Oil & Gas Lease No DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 7 Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A South Hobbs (G/SA) Unit DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form G101) for such proposals) Section 4 1 Type of Well 8 Well No 130 Gas Well Oil Well X Other 9 OGRID No 2 Name of Operator 157984 Occidental Permian Ltd. 10 Pool name or Wildcat 3 Address of Operator Hobbs (G/SA) HCR 1 Box 90 Denver City, TX 79323 4 Well Location Unit Letter F Feet From The Line 1403 Feet From The 1403 West North Section Townshin 19-S Range 38-E NMPM County Lea 11 Elevation (Show whether DF, RKB, RT GR, etc.) 3616' GL Pit or Below-grade Tank Application or Closure _____ Distance from nearest fresh water well ______ Distance from nearest surface water Depth of Ground Water Pit Type Below-Grade Tank: Volume bbls; Construction Material _mıl Pit Liner Thickness Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS **PLUG & ABANDONMENT** PULL OR ALTER CASING CASING TEST AND CEMENT JOB **Multiple Completion** OTHER. OTHER: Clean out/OAP/Acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103 For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1 RUPU & RU. RU wire line & shoot 4 holes in tubing. RD wire line. 60 2. ND wellhead/NU BOP. 0 leceived 3 POOH w/ESP equipment & tubing. 4. RIH w/bit & drill collars. Tag CIBP @4200'. RU power swivel & drill out CIBP & push to 4250'. Fell free ag TD @42983 RD pow swivel. POOH w/bit & drill collars 5. RU HES pump truck & acidize perfs 4070-4194', 4203-4244' w/4000 gal of 15% acid. Flush w/fresh water. (perf clean acid job) RD 6. RIH w/ESP equipment on 122 its of 2-7/8" tubing. Intake set @3991'. 7. ND BOP/NU wellhead. 8533⁰ 8 RDPU & RU. Clean location. RUPU 08/09/07 RDPU 08/16/07 I hereby certify that the information above is true and complete to the best of my knowledge and belef I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE DATE Administrative Associate 09/04/2007 TYPE OR PRINT NAME **TELEPHONE NO** Mendy Johnson E-mail address: mendy johnson@oxy.com 806-592-6280 For State Use Only OC RELO REPRESENTATIVE WATARY MATAGER 1 7 2007 APPROVED BY DAT TITLE

CONDITIONS OF APPROVAL IF AN

12.