Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		30-025-05243	
1301 W. Grand Ave, Artesia, NM 88210	1301 W. Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE	
District IV Santa Fe, INM 8/303		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		E-2504-4	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name State H
1. Type of Well: Oil Well  Gas Well  Other			8. Well Number 2
2. Name of Operator			9. OGRID Number 236378
Saber Resources, LLC			
3. Address of Operator		10. Pool name or Wildcat	
400 W. Illinois, Suite 950, Midland, Texas 79701		Denton, Wolfcamp	
4. Well Location			
Unit Letter H: 2210 feet from the North line and 990 feet from the East line			
Section 2 Township 15 S Range 37 E NMPM County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3604' G.L.			
Pit or Below-grade Tank Application or Closure			
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
12. Check Appropriate Box to indicate reactive of reduce, Report of Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			<del>_</del>
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🗆
OTHER:	П	OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
(1) RUPU & POH with the 2 7/8" tubing and sub pump equipment. Lay down all equipment.			
(2) RU wireline & RIH with a 5 ½" CIBP to 9100". Set CIBP @ 9100" and cap with 35" of cement.			
Temporarily Abandon the subject wellbore in the Wolfcamp zone & evaluate for any uphole potential.  (1) RUPU & POH with the 2 7/8" tubing and sub pump equipment. Lay down all equipment.  (2) RU wireline & RIH with a 5 ½" CIBP to 9100'. Set CIBP @ 9100' and cap with 35' of cement.  (3) Notify NMOCD of casing integrity test – load 5 ½" casing with corrosion inhibitior and fresh water. Pressure test the 5½" casing to 500# (with chart recorder) for 30 minutes to insure the TA'ed wellbore poses no threat to ground water contamination. RD pump truck.  (4) Evaluate well for possible uphole potential.			
(4) Evaluate well for possible uphole potential			
(1) Evaluate well for possible aprilote potential.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE A MAN I	TITLE		DATE @ /20/27
			DATE <b>4/20/07</b>
R. DOUGLAS KEATHLEY, VICE-PRESIDENT OPERATIONS  Type or print name  E-mail address: doug's saberresou vis. com Telephone No. 432-685-016			
101 State Ose Only			
$\mathcal{H}$			DATE SEP 2 6 2007
APPROVED BY: 104 DATE DATE DATE DATE DATE DATE DATE DATE			
Conditions of Approval (if any)			



