Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APROVED OMB NO. 1004-0137

(February 2005) OCD-HOBBS EXPIRES. March 31, 2007 BUREAU OF LAND MANAGEMENT Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an NMNM69596 abandoned well. Use Form 3160-3 (APD) for such proposals 6. It Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE - Other instructions on page 2 7. Unit or CA Agreement Name and No. NM 94480 A Type of Well 8 Well Name and No. Oil Well ☑ Gas Well Other **GAUCHO UNIT #5** 2. Name of Operator 9. API Well No. DEVON ENERGY PRODUCTION COMPANY, LP 3b. Phone No (include area code) 30-025-34149 10. Field and Pool, or Exploratory Area 405-552-4615 20 North Broadway, Ste 1500, Oklahoma City, OK 73102 OJO CHISO 4. Location of Well (Footage, Sec., T, R., M., or Survey Description) 11. County or Parish, State 1650 FSL 660 FEL H 30 T22S R34E ΝМ 12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OS SUBMISSIÓN Water Shut-Off Production (Start/Resume) Acidize Deepen Notice of Intent Fracture Treat Reclamation Well Integrity Alter Casing Other New Construction Recomplete ✓ Subsequent Report Casing Repair Change Plans ✓ Plug and Abandon Temporarily Abandon Final Abandonment Notice Plug Back Water Disposal Convert to Injection Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) 1. MIRU to P&A on 7/19/07. RIH and tagged CIBP at 5200'. Circulated wellbore with 9.5 mud. 2. Spot 35 Sx cement on top of CIBP at 5200'. Tagged TOC at 4989'. 3. Cut and pull 7" casing at 4100'. Spot 45 Sx cement at 4151'. Tagged TOC at 3994'. 4. Cut 9-5/8" casing at 2366'. Unable to pull casing. Spot 75 Sx cement at 2416. Tagged TOC at 2260'. 5. Spot 35 Sx cement from 2152' to 2260'. 6. Cut 9-5/8" casing at 2023'. Unable to pull casing. Spot 80 Sx cement at 2073'. Tagged TOC at 1925'. 7. Cut 9-5/8" casing at 1875'. Pull and lay down casing. Spot 75 Sx cement at 1925'. Tagged TOC at 1801'. 8. Circulated 40 Sx cement from 60' to surface. 9. Cut wellhead off and set dry hole marker. Plugged & Abandoned on 8/29/07. 14. I hereby certify that the foregoing is true and correct Engineering Technician Name (Printed/Typed) Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by PETROLEUM ENGINEER SEP 2 5 2007 AVID R. GLASS Title

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or

equitable title to those rights in the subject lease which would

entitle the applicant to conduct or operations thereon.

APPROVED AS TO PLUGGING OF THIS WELL BORE. LIABILITY UNDER BOND IS RETAINED UNTIL SURFACE RESTORATION IS COMPLETED Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

