Office	lew Mexico	Form C-103
<u>District I</u> Energy, Minerals a	nd Natural Resources	Revised March 25, 1999 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240  District II  ON GONGED VA TION DIVISION		30-025-05914
District II  1301 W. Grand Ave., Artesia, NM 88210  District III  1220 South St. Francis Dr		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410  Sonto Fo NIM 97505		STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.
87505		
SUNDRY NOTICES AND REPORTS ON (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEP!	7. Lease Name or Unit Agreement Name:	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Bertha Barber
PROPOSALS.) 1. Type of Well:		Dertila Baibei
Oil Well ⊠ Gas Well □ Other □		
2. Name of Operator Marathon Oil Company		8. Well No. #9
3. Address of Operator		O Paul name of Wildow
P.O. Box 552, Midland, TX 79702		9. Pool name or Wildcat  Monument (Blinebry)
4. Well Location		iviolidine nt (Billiebry)
Unit Letter E: 1,980 feet from the North line and 560 feet from the West line		
	0.0 - 07.1	
	O-S Range 37-I	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,556' GL; 3,572' KB		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON	☐ REMEDIAL WOR	K ALTERING CASING
TEMPORARILY ABANDON	☐ COMMENCE DR	<u> </u>
PULL OR ALTER CASING   MULTIPLE   CASING TAGOSTICAN		ABANDONMENT Med as to plugging of the Well Bore
COMPLETION	CEMENTURBilit	y under bond is retained until
OTHER:	OTHER: surface	restoration is completed.
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of		
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or		
recompilation.		
10/08/03 Notified OCD, Gary Wink. MIRU Triple N plugging equipment. NU BOP. RIH w/ 2-3/8" tbg to 5,090', tagged CIBP.		
Circulated hole w/ mud, pumped 25 sx C cmt 5,090 – 4,843'. Pumped 25 sx C cmt w/ 2% CaCl <sub>2</sub> 2,851 – 2,604'. POOH w/		
tbg, SDFN.		
10/09/03 Notified OCD, Oscar. Tagged cmt @ 2,580'. Cut and pulled 2,190' 5½" casing. RIH w/ tbg and າກພິກີຂໍດີ 40 sx C		
cmt 2,250 – 2,060'. SDFN.		
40/40/02 Notified OCD Buddy. Toggod omt @ 2.050; D	umanad 25 av C amb 4 500	
<b>10/10/03</b> Notified OCD, Buddy. Tagged cmt @ 2,059'. P surface. POOH w/ tbg, RDMO.	umped 35 SX C cmt 1,500	J-1,371. Circulated 105 samport 317 to
canada. 1 deri in tag, 1 anie.		12 00 PC
10/13/03 Cut off wellhead, installed marker, cut off ancho	rs. Emptied & backfilled	pit and cellar.
		60
		Sp. C. T. KeOE
I hereby certify that the information above is true and complete	to the best of my knowledg	e and belief.
SIGNATURE	ITLE Enginee	er DATE
Type or print name  James F. Newman, P.E.  Telephone No. 432,687-1994  (This space for State use)  OC DISTRICT SUPERVISOR/GENERAL MANUAL PRINTS 1 2003		
OC DISTRICT SUPERVISOR DET 2 1 2003		
APPPROVED BY HOW TITLE DATE		
Conditions of approval, if any:		