

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-25651
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	H.P. SAUNDERS
8. Well No.	2
9. Pool Name or Wildcat	TUBB OIL AND GAS (OIL)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3342' GL	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>J</u> : <u>1650</u> Feet From The <u>SOUTH</u> Line and <u>2310</u> Feet From The <u>EAST</u> Line Section <u>7</u> Township <u>22-S</u> Range <u>38-E</u> NMPM <u>LEA</u> COUNTY
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ RECOMPLETE TO TUBB ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-16-07: MIRU. UNSET TAC.
7-17-07: TIH W/WS & BIT TO 6925.
7-18-07: GIH W/CIBP & SET @ 6900. RUN GR/CBL/CCL LOG FR 6900-5800.
7-19-07: TIH W/PKR TO 6900. PU 11 JTS. TAG CIBP. PULL UP 22'. SET PKR @ 6878. TIH W/CIBP & SET @ 6878. DUMP 35' CMT ON CIBP.
7-20-07: PERF 6364-6366, 6371-6376, 6406-6416, 6430-6440, 6510-6520, 6557-6567. TIH W/PPI TOOLS 212 JTS TO 6601. MARK SETTINGS OUT OF THE HOLE TO 204 JTS, 6345.
7-23-07: ACIDIZE PERFS 6364-6567 W/1200 GALS 15% NEFE. REL PKR. FLUSH 20 BBLS ANN. PUH & SET PKR @ 6351'. SN @ 6327. SWAB.
7-24-07: REV CIRC 50 BBLS TO CLEAN PARAFFIN. SWABBING.
7-25-07: TREAT PERFS 6364-6567 W/4500 GALS 15% NEFE HCL.
7-26-07: SWABBING. UNSET PKR.
7-27-07: TIH W/PKR & SET @ 6231.
7-31-07: FRAC W/37,765 GALS YF125.
8-01-07: TAG @ 6512'.
8-02-07: LOCATION CLEAN UP.
8-03-07: REL PKR. TIH W/NOTCH COLLAR TO 5040.
8-06-07: C/O SAND FR 6620-6800. TIH W/PRK & SET @ 6333.
8-07-07: SWABBING.
8-08-07: SWABBING.
8-09-07: REL PKR. TIH W/PROD TBG.
8-10-07: TIH W/PMP & RODS.
8-13-07: SPACE OUT WELL. RIG DOWN. FINAL REPORT. W/O COMPLETION TEST.
8-31-07: ON 24 HR OPT. PUMPING 52 OIL, 46 GAS, & 60 WATER. GOR-885.



I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist

DATE 9/10/2007

TYPE OR PRINT NAME Denise Pinkerton

Telephone No. 432-687-7375

(This space for State Use)

APPROVED 2A Brunson Drinkard Abo South TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE OCT 10 2007