Submit 3 Copies To Appropriate District Office	State of New Me		Form C-103
District I	Energy, Minerals and Natu	ıral Resources	May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONCEDIATION	I DIVICIONI	30-025-30698
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St. Fra		STATE / FEE 🗌
District IV	Santa Fe, NM 8	/505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTI	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		WEST LOVINGTON UNIT	
PROPOSALS)		8. Well Number 66	
	Gas Well  Other		
2. Name of Operator			9. OGRID Number 241333
	RON MIDCONTINENT, L.P.		10. Pool name or Wildcat
3. Address of Operator 15 SM	MITH ROAD, MIDLAND, TEXA	S 79705	LOVINGTON UPPER SAN ANDRES
4. Well Location			
Unit Letter: P 135 feet fro	m the SOUTH line and 1300 feet	from the EAST line	
Section 5 Township	17S Range 36E	NMPM	County LEA
	11. Elevation (Show whether DF	R, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application 🔲 o	r Closure 🗌		
Pit typeDepth to Groundwa	aterDistance from nearest fresh	water well Dist	ance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	nstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN	TENTION TO:	l SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🗍	PLUG AND ABANDON	I REMEDIAL WORI	K $\square$ ALTERING CASING $\square$
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	PLUG AND ABANDON  CHANGE PLANS	REMEDIAL WORI	K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPL	COMMENCE DRI	K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐ ☐ F JOB ☐
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPL	REMEDIAL WORI	K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPL	REMEDIAL WORI COMMENCE DRI CASING/CEMENT OTHER: TA WIT	K
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DULL OR Starting any proposed we of starting any proposed we	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPL   leted operations. (Clearly state all  rk) SEE RULE 1103. For Multiple Complete C	REMEDIAL WORI COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and	ALTERING CASING   LLING OPNS. P AND A  T JOB  TH CHART  I give pertinent dates, including estimated date  tach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or compostarting any proposed woor recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detection Clearly state all brk). SEE RULE 1103. For Multip	REMEDIAL WORI COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ple Completions: Att	ALTERING CASING LLING OPNS. P AND A DIF JOB DIFFERENCE STATES THE CHART digive pertinent dates, including estimated date tach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or compof starting any proposed woor recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detected operations. (Clearly state all ork). SEE RULE 1103. For Multiple Company of the company	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ple Completions: Att	ALTERING CASING LLING OPNS. P AND A DIFFERENCE PAND A PAND A DIFFERENCE PAND A DIFFE
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING DULL OR ALTER CASING DULL OR Starting any proposed we or recompletion.  9-10-07: NOTIFIED NMOCD.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detect operations. (Clearly state all brk). SEE RULE 1103. For Multiput TEST CSG TO 520 PSI FOR 30	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ple Completions: Att MINUTES. CHART	ALTERING CASING LLING OPNS. PAND A DIFFERENCE PA
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR A	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detected operations. (Clearly state all ork). SEE RULE 1103. For Multiple TEST CSG TO 520 PSI FOR 30 PHED. ORIGINAL CHART HAS	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ole Completions: Att MINUTES. CHART BEEN MISPLACEI	ALTERING CASING LLING OPNS. P AND A DIF JOB DIFFERENCE DIFFERENCE DIFFERENCE DATE OF A STATE OF A S
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR A	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detect operations. (Clearly state all brk). SEE RULE 1103. For Multiple TEST CSG TO 520 PSI FOR 30 CHED. ORIGINAL CHART HAS 09-5062.	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ple Completions: Att MINUTES. CHART BEEN MISPLACEI	ALTERING CASING LLING OPNS. P AND A DIF JOB P AND A DIF JOB DIFFERENCE DIFFERENCE PART DIFFERE
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or compostarting any proposed we or recompletion.  9-10-07: NOTIFIED NMOCD. (COPY OF CHART IS ATTACCIBP SET @ 4634. PERFS 47)  WELL IS TEMPORARILY APPROPERTMENT OF TEMPORARILY APPROPER	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL MULTIPLE COMPL Detect operations. (Clearly state all book). SEE RULE 1103. For Multiple TEST CSG TO 520 PSI FOR 30 PHED. ORIGINAL CHART HAS 109-5062.	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ole Completions: Att MINUTES. CHART BEEN MISPLACED  emporary 9/	ALTERING CASING LLING OPNS. P AND A DIFFERENCE CASING P AND A DIFFEREN
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or compof starting any proposed woor recompletion.  9-10-07: NOTIFIED NMOCD. (COPY OF CHART IS ATTACCIBP SET @ 4634. PERFS 47)  WELL IS TEMPORARILY ABOUT TEMPORARILY ABOU	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL MULTIPLE COMPL MULTIPLE COMPL MULTIPLE COMPL CHART HAS 109-5062.  ANDONED APPLOVAL OF TABLE A	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ole Completions: Att MINUTES. CHART BEEN MISPLACEI  emporary oires	ALTERING CASING LLING OPNS. P AND A DIF JOB PAND A DIF JOB DIF JOB DIF THE CHART Digits of proposed completion of FOR NMOCD PART DIFFERENCE OF THE CHART DIFFERENCE OF THE CHA
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or compostarting any proposed we or recompletion.  9-10-07: NOTIFIED NMOCD. (COPY OF CHART IS ATTAC CIBP SET @ 4634. PERFS 47)  WELL IS TEMPORARILY ABOUT	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detect operations. (Clearly state all brk). SEE RULE 1103. For Multiple TEST CSG TO 520 PSI FOR 30 CHED. ORIGINAL CHART HAS 109-5062.  ANDONED APPLOVAL OF ABANDONED ABANDONMENT EXP	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ole Completions: Att MINUTES. CHART BEEN MISPLACEI  emporary 9 Dires	ALTERING CASING LLING OPNS. P AND A DIF JOB P AND A DIF JOB DIFFERENCE DIFFER
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or compostarting any proposed we or recompletion.  9-10-07: NOTIFIED NMOCD. (COPY OF CHART IS ATTAC CIBP SET @ 4634. PERFS 47)  WELL IS TEMPORARILY AE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detect operations. (Clearly state all ork). SEE RULE 1103. For Multiple TEST CSG TO 520 PSI FOR 30 PHED. ORIGINAL CHART HAS 109-5062.  ANDONED APPLOVAL OF A ABANDONED ABANDONMENT EXP	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ole Completions: Att MINUTES. CHART BEEN MISPLACED emporary	ALTERING CASING LLING OPNS. PAND A DIFFERENCE CASING PAND A DIFFERENCE
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or compostarting any proposed we or recompletion.  9-10-07: NOTIFIED NMOCD. (COPY OF CHART IS ATTACCIBP SET @ 4634. PERFS 47  WELL IS TEMPORARILY AE  I hereby certify that the information grade tank has been will be constructed or	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL MULTIPLE COMPL MULTIPLE COMPL MULTIPLE COMPL CHART HAS 109-5062.  ANDONED APPLICATION ADMINISTRATION Abandonment Expansion of the classed according to NMOCD guidelines.	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ole Completions: Att MINUTES. CHART BEEN MISPLACEI Comporary Oires  Dest of my knowledge  The general permit To	ELING OPNS. PAND A DISTRICT TO THE CHART Is give pertinent dates, including estimated date tach wellbore diagram of proposed completion of FOR NMOCDO 100 100 100 100 100 100 100 100 100 10
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or compostarting any proposed we or recompletion.  9-10-07: NOTIFIED NMOCD. (COPY OF CHART IS ATTACCIBP SET @ 4634. PERFS 47)  WELL IS TEMPORARILY ABOUT IN THE PROPERTY IS TEMPORARILY ABOUT IS TEMPORARILY ABOUT IN THE PROPERTY IS TEMPORARILY ABOUT IT THE PROPERTY IS TEMPORARILY ABOUT IN THE PROPERTY IS TEMPORARILY ABOUT IT THE PROPERTY IS THE PROPERTY IN THE PROPERTY IS THE PROPERTY IS THE PROPERTY IS THE PROPERTY IN THE PROPERTY IS THE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Detect operations. (Clearly state all brk). SEE RULE 1103. For Multiple TEST CSG TO 520 PSI FOR 30 CHED. ORIGINAL CHART HAS 109-5062.  ANDONED ADDITIONAL CHART EXPLAND ABANDONMENT EXPLAND ABANDONMENT EXPLAND ABANDON COMPLETE TO THE Closed according to NMOCD guidelines (1)	REMEDIAL WORL COMMENCE DRI CASING/CEMENT OTHER: TA WIT pertinent details, and ole Completions: Att MINUTES. CHART BEEN MISPLACEI  COMPORTY OIR COMPO	ALTERING CASING LLING OPNS. PAND A DIT JOB PAND A DIT JOB DIT H CHART digive pertinent dates, including estimated date tach wellbore diagram of proposed completion of FOR NMOCED 2007 To Proposed Completion of Pand District Com
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or compostarting any proposed we or recompletion.  9-10-07: NOTIFIED NMOCD. (COPY OF CHART IS ATTACCIBP SET @ 4634. PERFS 47)  WELL IS TEMPORARILY AE  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	is / /	, a general per init	ALTERING CASING LLING OPNS. P AND A DIT JOB P
grade tank has been/win be constructed in	nkyston title	, a general per init	or an (attached) after hanve OCD-approved plan
SIGNATURE SIGNATURE	TITLE erton E-mail address: leak	Regulatory Specialis	st DATE 10-26-07  Telephone No. 432-687-7375
SIGNATURE  Type or print name  For State Use Only	TITLE erton E-mail address: leak	Regulatory Specialis  cejd@chevron.com	Telephone No. 432-687-7375  WSTAFF MANAGET OCT 3 0 2007
Type or print name  For State Use Only  APPROVED BY:  Denise Pinke	TITLE erton E-mail address: leak	Regulatory Specialis  cejd@chevron.com	st DATE 10-26-07  Telephone No. 432-687-7375
SIGNATURE  Type or print name  For State Use Only	TITLE erton E-mail address: leak	Regulatory Specialis  cejd@chevron.com	Telephone No. 432-687-7375  WSTAFF MANAGET OCT 3 0 2007

