

NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E. Director

Oil Conservation Division

20-Dec-07

RKI EXPLORATION & PRODUCTION, LLC

3817 NW EXPRESSWAY SUITE 950 OKLAHOMA CITY OK 73112-

LETTER OF VIOLATION - Inactive Well(s)

Dear Operator:

A review of our records and recent inspection(s) indicate that the subject well(s) has been shut-in for an extended period of time. Rule 201 of the Rules and Regulation of the Oil Conservation Division provides that a well may be shut-in no longer than sixty days after suspension of drilling operations, upon determining that ther well is no longer usable (e.g., a dry hole), or one year after last production. To comply with guidelines as established in the Rules and Regulations, corrective actions must be taken immediately and the well(s) brought into compliance.

The detail section below indicates preliminary findings and/or probable nature of the violation.

The following options are available:

- 1. Immediately restore the well(s) to production, injection or disposal as applicable.
- 2. Request 'Temporary Abandoned' status pursuant to Rule 203, which requires that you set a plug and conduct a mechanical integrity test.
- 3. Submit a proposal to 'Plug and Abandon' the well(s) pursuant to Rule 202, proceed with plugging procedures on a timely basis after the proposal has been evaluated, amended and/or approved.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

IDLE WELL INSPECTION DETAIL SECTION

TORO 16 STATE 001

M-16-19S-35E

30-025-35054-00-00

Inspection No. iLWH0735233487

Inspection Date:

12/18/2007 9:18:03 AM

Corrective Action Due by: 3/22/2008

Type Inspection Routine/Periodic Inspector

*Significant Non-Compliance?

Comments on Inspection:

Buddy Hill

Violation? Yes

Nο

idle Well (Rule 201),, Well is off electric.. NEEDS TO BE T/A, P/A OR PUT BACK IN USE.. FIRST

NOTICE

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



RKI EXPLORATION & PRODUCTION, LLC 3817 NW EXPRESSWAY SUITE 950 OKLAHOMA CITY, OK 73112