Form 3160-5 (April 2004)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-	PEROF
------	-------

FORM APPROVED OM B No 1004-0137 Expires: March 31, 2007

EAPHes. Willen 51, 2007						
5.	Lease Se	nal No.				
(	FEE					
	-	4.11				-

SUNDRY NOTICES AND REP	FEE FEE		
Do not use this form for proposals to abandoned well. Use Form 3160 - 3 (A	6 If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE- Other instru	7 If Unit or CA/Agreement, Name and/or No.		
Type of Well     Oil Well     Gas Well     Other	NMNM71917 (SW-977)		
2. Numa of Operator	8. Well Name and No.  Martin #1		
Manhattan Petroleum, Inc.			
3a Address P. O. Box 35888, Tulsa, OK 74153-0888	9. API Well No. 30-025-24882  10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T, R, M, or Survey Description)	Sawyer S S S S S S S S S S S S S S S S S S S		
M Sec 9-T9S-R38E N	11 County or Parish, State		
12. CHECK APPROPRIATE BOX(ES) TO I	NDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION	: B 12 A	
Notice of Intent	Deepen Production (S Fracture Treat Reclamation New Construction Recomplete		
Final Abandonment Notice Change Plans Convert to Injection	Plug and Abandon Temporarily 2 Plug Back Water Dispose	Abandon / O // O	
Attach the Bond under which the work will be performed or provide following completion of the involved operations. If the operation re testing has been completed. Final Abandonment Notices shall be fil determined that the site is ready for final inspection.)  PLUG #1: Circulated and worked to 3,474'. NMOCD Gar RIH tag @ 3,058.  PLUG #2: Perforate 4 squeeze holes @ 2892'. Could no 2,942'. POH and WOC. RIH tag @ 2,568'. POH. Shoot sq Finished flush and attempt to release packer, drag up hole PLUG #3: Tag plug @ 1,758'. Perf @ 436'. Sqz 25 sacks PLUG #4: Perf @ 100'. Circulate cement from 100' to a	sults in a multiple completion or recompletion ed only after all requirements, including reclary Wink & Maxey Brown approved sport pump into perfs. NMOCD approved sueeze holes @ 2,300'. Set packer @ 2,01e 10', would not move. Back off safety cost. Tag plug @ 268'.	n in a new interval, a Form 3160-4 shall be filed once mation, have been completed, and the operator has t 25 sack plug. POH to above plug & WOC.  Spot 25 sacks across perfs. Spot 25 sacks @ 0'. Pump 25 sacks. Circulation up annulus.  ollar on top of packer, Leave @ 2,020'.	
PLUG #4: Perf @ 100'. Circulate cement from 100' to s  Remove manway cover and clean out closed-top fiberglass	ACCEPTED FOR RECORD		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title Regulatory Administ	DEC 1 2007	
Signature (Swan		BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE	
THIS SPACE FOR FE	DERAL OR STATE OFFICE	USE	
Conditions of approval, if any, are attached. Approval of this notice do	DISTRICT SUPERILESOR/GENER	AL MANA BEE DEC 20 2007	
certify that the applicant holds legal or equitable title to those rights in the which would entitle the applicant to conduct operations thereon.	the subject lease Office	· •	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.