

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor Joanna Prukop Cabinet Secretary

Mark E. Fesmire, P.E. Director Oil Conservation Division

Field Inspection Program "Preserving the Integrity of Our Environment"

07-Jan-08

## PHOENIX HYDROCARBONS OPERATING CORP

PO BOX 3638 MIDLAND TX 79702

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

DICDECTION	TARMER	CECTION
INSPECTION	DEIAH	SECLION

CHANEY FEDERAL No.001 L-17-11S-33E 30-025-22554-00-00 Inspection \*Significant Corrective Type Inspection Inspector Violation?

Inspection No. Date Non-Compliance? Action Due By:

01/04/2008 iMGB0800443797 Routine/Periodic Maxey Brown Yes No 2/8/2008 Violations

Surface Leaks/Spills General Housekeeping (Rule 114)

Comments on Inspection: Valves or other equipment leaking. Fix ASAP. (115) NEED TO REPAIR BROKEN VALVE ON HEATER TREATER, LEAKING GAS AND LIQUIDS. RULE 116. ALSO NEED TO REMOVE

SURPLUS, UNLABEL DRUM CONTAINING UNKNOWN PRODUCT FROM NORTHSIDE OF PUMPING UNIT. RULE 13. THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB.

TILLY No.001 P-18-11S-33E 30-025-22702-00-00

Inspection \*Significant Corrective **Type Inspection** Inspection No. Violation?

Date Inspector Non-Compliance? Action Due By: 01/04/2008 Routine/Periodic iMGB0800446616 Maxey Brown Yes

No 2/8/2008 Violations

Absent Well Identification Signs (Rule 103)

Surface Leaks/Spills

General Housekeeping (Rule 114)

Comments on Inspection: NO Well Sign (Rule 103). NEED TO INSTALL WELL SIGN, ALSO LOAD LINE VALVE ON TANK LEAKING OIL. RULE 13. NEED TO REMOVE OLD POLISH ROD LINER, 2 JUNK

SUCKER RODS AND UNUSED PIPING (STEEL AND POLY) FROM LOCATION. RULE 115.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

**COMPLIANCE OFFICER** 

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



014H15215335 \$0.410 01/07/2008 Mailed From 88240

PHOENIX HYDROCARBONS OPERATING CORP PO BOX 3638 MIDLAND TX 79702