



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Field Inspection Program

"Preserving the Integrity of Our Environment"

10-Jan-08

PRIDE ENERGY COMPANY

P.O. BOX 701602

TULSA OK 74170-1602

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

BAGLEY No.001				A-9-11S-33E	30-025-20610-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
01/10/2008	Drill / Deepen / Re-Entry	Maxey Brown	Yes	No	4/14/2008	iMGB0801029601	
Comments on Inspection:		WELL NEEDS TO BE RETURNED TO PROD., T/A'D OR P/A'D. NEED TO SUBMIT CURRENT C-103 TO REFLECT ANY WORK DONE SINCE 4-2007. ALSO REMOVE FLUID FROM PIT AND CLOSE PIT. RULE 50. REMOVE UNUSED DRILLING EQUIP AND CLEAN TRASH, 5 GAL PLASTIC BUCKETS, MISC. JUNK FROM LOCATION. RULE 13. THIS IS 1 ST LETTER OF NON-COMPLIANCE.					

SOUTH FOUR LAKES UNIT No.009				J-35-11S-34E	30-025-31188-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
01/09/2008	Routine/Periodic	Maxey Brown	Yes	No	4/13/2008	iMGB0800958422	
Violations		General Housekeeping (Rule 114)					
Comments on Inspection:		Location needs attention. Equipment OK. NEED TO REMOVE PILE OF OLD PIT LINING FROM NW CORNER OF LOCATION. RULE 114. THIS IS 1ST LETTER OF NON-COMPLIANCE.					


SOUTH FOUR LAKES UNIT No.016

J-2-12S-34E

30-025-37248-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
01/10/2008	File and Compliance Review	Maxey Brown	Yes	No	2/14/2008	iMGB0801031854
Comments on Inspection:		WELL NEEDS TO BE PLUGGED. RULE 201. THIS IS 2ND LETTER OF NON-COMPLIANCE.				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.



Sincerely,


COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER

014H15215335

\$0.410

01/10/2008

Mailed From 88240

US POSTAGE

PRIDE ENERGY COMPANY
P.O. BOX 701602
TULSA OK 74170-1602