

Submit 3 Copies To Appropriate  
District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised June 10, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30 025 28391
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name New Mexico BG State NCT 2
8. Well Number 2
9. OGRID Number 213190
10. Pool name or Wildcat: Sauders:Permo Penn Upper

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other (Injection) <input type="checkbox"/>	7. Lease Name or Unit Agreement Name New Mexico BG State NCT 2
2. Name of Operator CrownQuest Operating, LLC	8. Well Number 2
3. Address of Operator P O. Box 53310, Midland, TX 79710	9. OGRID Number 213190
4. Well Location (Surface)  Unit Letter <u>H</u> : <u>2310</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line  Section <u>16</u> Township <u>14S</u> Range <u>33E</u> NMPM Lea County	10. Pool name or Wildcat: Sauders:Permo Penn Upper
11. Elevation (Show whether DR, RKB, RT, GR, etc.): <u>4213 GR</u>	

12 Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please see proposed plugging procedure attached, along with wellbore diagram.  
Anticipate plugging upon approval.

SEE CORRECTIONS ON A/A PROCEDURE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Regulatory Agent DATE: 12-4-07



Type or print name Ann E. Ritchie E-mail address: ann.ritchie@wtor.net Telephone No. 432 684-6381

(This space for State use)

APPROVED BY Hayden W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JAN 10 2008  
Conditions of approval, if any:

THE OIL CONSERVATION DIVISION MUST  
BE NOTIFIED 24 HOURS PRIOR TO THE  
BEGINNING OF PLUGGING OPERATIONS.

*Crown Quest Operating, LLC*  
**New Mexico BG State NCT-1 #2**



WI 1  
 NRI 0.875

*API # 30-025-28391*

*Drilled Feb 1959*

Procedure:

- 1 Circulate hole w/ 9 ppg plugging mud.
- 2 RIH & bail 35' of cmt on CIBP @ 9660'
- 3 Free point 5.5" csg & cut @ 7700' & pull
- 4 Spot 1st plug 7600-7800' 50 sxs — WOC + TAG 50' ABOVE CUT
- 5 Spot 2nd plug 35 sxs
- 6 Spot 3rd plug 4050-4200' 50 sxs — WOC + TAG
- 7 Spot 4th plug 2600-2800' 75 sxs
- 8 Spot 5th plug 300-400' 35 sxs — WOC + TAG
- 9 Spot 6th plug 0-50' 20 sxs
- 10 Cut off wellhead & install dry hole marker

	Top	Bottom	Vol (cf)	Sxs
Plug 1	7600	7800	54.5	46
Plug 2	5500	5600	40.9	35
Plug 3	4050	4200	63.0	53
Plug 4	2600	2800	86.5	73
Plug 5	300	400	43.3	37
Plug 6	0	50	20.5	17

ID 5.5	4.98 in
ID 8-5/8	8.907 in
ID 7-7/8 hc	8.6625 in

Cp 5.5	0.13527 cf/ ft
Cap 8.625	0.43270 cf/ ft
Cap 7.875	0.40927 cf/ ft