



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor
Joanna Prukop
Cabinet Secretary

Mark E. Fesmire, P.E.
Director
Oil Conservation Division

Field Inspection Program
"Preserving the Integrity of Our Environment"

24-Jan-08

TEXLAND PETROLEUM-HOBBS, LLC
777 MAINSTREET, SUITE 3200
FORT WORTH TX 76102

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

YP 9 STATE No.001				A-9-17S-36E	30-025-37684-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
01/24/2008	Plugged Well Surface Restor	Mark Whitaker	Yes	No	4/28/2008	iMAW0802430503
Comments on Inspection: Dry hole marker incomplete. Need to add API No. Location in good shape. MW						

CP 3 STATE No.001				P-3-17S-36E	30-025-37845-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
01/24/2008	Plugged Well Surface Restor	Mark Whitaker	Yes	No	4/28/2008	iMAW0802430182
Comments on Inspection: DO NOT RELEASE. Well sign, pieces of boards, and piece of junk csg need to be removed. Area west of marker where unit set needs to be leveled. Section No. and API No. need to be added to dry hole marker. MW						

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.


Sincerely,


COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

NRD
CONSERVATION DIVISION
5 N FRENCH DRIVE
BBS NM 88240



014H15215335
\$0.410
01/24/2008
Mailed From 88240

US POSTAGE

TEXLAND PETROLEUM-HOBBS, LLC
777 MAIN STREET, SUITE 3200
FORT WORTH, TX 76102