

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON Governor Joanna Prukop Cabinet Secretary Mark E. Fesmire, P.E. Director Oil Conservation Division

Field Inspection Program "Preserving the Integrity of Our Environment"

22-Oct-07

OIL & GAS OPERATIONS 3206 W WADLEY MIDLAND TX 79705 JAN 2 3 2008

RECEIVED



Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION							
STATE H 17 No.001 Inspection Date Type Inspection			Inspector	Violation?	E-17-20S-37E *Significant Non-Compliance?	30-025-20100-00- Corrective Action Due By:	00 Inspection No.
10/18/2007	Routine/Periodic		Buddy Hill	Yes	No	1/21/2008	iLWH0729158706
Violations							
	General Housek	eeping (Rule 114)	H				
Comments on Inspection:		VERY TRASHY @ BATTERYCLEAN UP WOULD BE GOODGENERAL HOUSEKEEPING IS BADOLD TANK TOPS AND BOTTOMS AND JUNK EQUIPMENT AROUND BATTERY SITE NEEDS TO BE CLEANED UPFIRST NOTICE					

1-2508 Mill

Greg Short 3206 W Wadley Ave Midland TX 79705 (432) 520-7042

Oil & Gas Operations

Monday, January 21, 2008

Mr. Buddy Hill Oil Conservation Division, Hobbs District 1625 N. French Drive Hobbs, NM 88240

RECEIVED

JAN 2 3 2008

Re: Letter of Violation, State H-17 Lease

HOBBS OCD

Dear Mr. Hill:

Thank you for your letter in which you point out that some battery cleanup is desirable at the subject location. We have located a facility that will accept our junk metal, and we will have it removed from the battery site by the end of March 2008. The old material was left by the previous operator, and we have removed the greater part of the junk, but, as you pointed out, we have more work to do.

Since your letter, a couple of things have hindered and delayed our progress on the housekeeping at the site. To reduce the possibilities of oil and/or water spills at the site, we have reworked both the water and oil dumps and piping at the facility. Increased pressure in the Rice water disposal system (due to their construction) increased the likelihood of a battery spill. We worked with them, improved our fluid piping, and believe that problem is solved. Also, the road has been improved to provide better access to the site.

In addition I have been ill and out of commission for a couple months. I'm better now and will be working with the pumper to make the improvements needed with respect to the overall appearance of the facility. We ask for your patience with us, as we also desire to progress with the general clean up.

Thank you for your patience and assistance in this matter.

Sincerely,

0K. 98