

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

DISTRICT I
P O Box 1980, Hobbs, NM 88240

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
811 S. 1st Street, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.	30-025-28958
5. Indicate Type of Lease	FED <input checked="" type="checkbox"/> STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH HOBBS (G/SA) UNIT
8. Well No.	443
9. Pool name or Wildcat	HOBBS (G/SA)


SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/> Injector	
2. Name of Operator Occidental Permian Ltd.	
3. Address of Operator 1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200	
4. Well Location Unit Letter <u>P</u> : <u>1300</u> Feet From The <u>SOUTH</u> Line and <u>106</u> Feet From The <u>EAST</u> Line Section <u>30</u> Township <u>18S</u> Range <u>38E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT GR, etc) 3648 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: TA Pressure <u>Injection</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103

1. Pull bare tbg and packer.
2. Set Plug over perfs at approximately 3970.
3. Notify NMOCD of packer test.
4. Disconnect surface equipment and TA well.

Federal Form 3160 will be filed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D. Nelson TITLE PROD ENGR ADVISOR DATE 12/2/07
TYPE OR PRINT NAME D. NELSON TELEPHONE NO 505/397-8200

(This space for State Use)
APPROVED BY Harry W. Wink TITLE OC FIELD REPRESENTATIVE II / STAFF MANAGER DATE FEB 06 2008
CONDITIONS OF APPROVAL IF ANY:

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.