Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources 1625 N French Dr., Hobbs, NM 88240	May 27, 2004 WELL API NO.
District II 1301 W Grand Ave , Artesia, NM 88210 OIL CONSERVATION DIVISION 1220 See at le St. Francis Dr.	30-025-36643 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd, Aztec, NM 87410 District IV 1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr, Santa Fe, NM 87505	6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Keller 4 State
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 1
2. Name of Operator	9. OGRID Number 6137
Devon Energy Production Company, LP 3. Address of Operator	10. Pool name or Wilcat
20 North Broadway, Oklahoma City, Oklahoma 73102-8260 (405) 552-8198	Delaware
4. Well Location	
Unit Letter K: 1980 feet from the South line and 1475 feet from the West line Section 4 Township 23S Range 35E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	· · · · · · · · · · · · · · · · · · ·
3537' GL Pit or Below-grade Tank Application or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Co	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	LLING OPNS. P AND A
OTHER: OTHER Recompletion Report 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 7/26/07 – 11/06/07	
MIRU PU. POH with plungers. RIH with blanking plug and set in R-nipple at 12,784'. Pressured up to 1000 psi and held good. ND wellhead and NU BOP. Released on/off tool and POOH with tubing. Finish POH with tubing and on/off tool. RIH with RBP and set at 12,001'. Test RBP and casing to 3000 psi – held good. Dumped sand to give 10' on top of RBP. RU wireline and perforate Bone Springs from 9938' to 9952'; 3 SPF. POH with wireline and RD. RIH with treating packer and set at 9881'. Tested casing to 1000 psi – held good. Swab well. Acidize perfs with 2,500 gallons 15% HCl acid. Swab well. RU and pumped 30 bbls 2% KCl down tubing. Release packer and POH with tubing and packer. RIH with packer and set at 9889'. Loaded and tested casing. Frac with 46,000 gallons Spectra Star 2500 and 51,875 # of Super LC 20/40 sand. Swab well. ND tree and NU BOP. Released packer and POOH with packer and tubing. RIH with tubing, pump, and rods. Set pumping unit. Hang well on. Bone Springs was unsuccessful. MIRU PU. Unseated pump and POH with rods and pump. Tested casing and RBP to 3000 psi – held good. Dumped 3 sacks sand on top of RBP at 8836'. POH with tubing and on/off tool. RU and perforate 8713-8722', 8650-8654', 8638-8645', 8628-8636', 8620-8625', and 8584-8593'. Finish RIH with packer and set at 8543'. Loaded casing and pressured to 1000 psi. – held good. Swabbed well. Acidize with 4000 gallons 7.5% Pentol acid. Swab well. Released packer and POH with tubing and packer. ND BOP and NU Frac valve. Frac Delaware with 65,500 gallons Spectra Star 2500. RIH with production tubing. RIH with pump and rods. Hung well on. Pressured tubing to 500 psi – held good. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any put or below-	
grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan SIGNATURE DATE12/11/07	
Type or print name Norvella Adams E-mail address: norvella.adams@dvn.com Telephone No. 405-552-8198 For State Use Only	
APPROVED BY: This Welliam OC DISTRICT SUPERVISOR GENERAL MANAGEDATE FEB 15 2008 APPROVED BY: THE SUPERVISOR GENERAL MANAGEDATE FEB 15 2008 APPROVED BY: The Supervisor of Approval (if any): APPROVED BY: The	