

UNITED STATES  
DEPARTMENT OF THE INTERIOR **OCD-HOBBS**  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB NO. 1004-0137  
Expires March 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		FEB 18 2008		5. Lease Serial No. LC 046164 A	
2. Name of Operator XTO Energy Inc.		HOBBS OCD		6. If Indian, Allottee or Tribe Name	
3a. Address 200 LORAIN, STE. 800 MIDLAND, TX 79701		3b. Phone No. (include area code) 432-620-6740		7. If Unit or CA/Agreement, Name and/or No. NM 70948B	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980 Feet from the South line and 660 Feet from the West line; Unit Letter L, Section 23, T-20-S, R-36-E, NMPM, Lea County, New Mexico				8. Well Name and No. EUNICE MONUMENT 917 SOUTH UNIT B	
				9. API Well No. 30-025-04293	
				10. Field and Pool, or Exploratory Area EUNICE MONUMENT; GRAYBURG SAN ANDRES	
				11. County or Parish, State LEA NM	

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Extend TA</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	<u>Status</u>
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

MIT CHART ATTACHED - OK. TEST WAS PERFORMED ON 1/24/08.

XTO is currently evaluating this well and at this time would like to request an extension of the TA Status until this evaluation can be completed.

SEE ATTACHED FOR  
CONDITIONSAfter 5-13-08 the well must be online  
or plans to P & A must be submitted.

ACCEPTED FOR RECORD

FEB 13 2008

LES BABYAK  
PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Kristy Ward

Title

Regulatory Analyst

Date 01/31/08

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

OC DISTRICT SUPERVISOR/GENERAL MANAGER

Title


Office

Date

FEB 26 2008

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



*Pat Hinchey*  
*BLM - 92000 Test*

*Alan M. [unclear]*  
*XTO*

XTO ENERGY

EMSU - B #917

01-24-2008

UNIT L, SEC 23, T20S, R36E

KEY 407

DAVIN MACIAS

TRK #0113237

01-24-2008

CHART RECORDER CALIBRATED

01-21-2008

TUB ⊗ PSI  
SURFACE ⊗ PSI  
INT. ⊗ PSI  
CASING ⊗ PSI



United States Department of the Interior  
BUREAU OF LAND MANAGEMENT  
Carlsbad Field Office  
620 E. Greene St.  
Carlsbad, New Mexico 88220  
Tel. (505) 234-597  
Fax (505) 234-5927



February 12, 2008

XTO Energy Inc.  
200 Loraine, STE. 800  
Midland, TX. 79701

RE: Eunice Monument South Unit Wells:  
103,123,202,210,335,371,415,418,854,876,878,886,896 and 917

Gentlemen:

Our records indicate that the above well is Shut-in (SI) or Temporarily Abandoned (TA). The Bureau of Land Management (BLM) and Minerals Management Service (MMS) definition of a shut-in well is a completion that is physically and mechanically capable of production in paying quantities or capable of service use. The definition of a temporarily abandoned well is a completion that is not capable of production in paying quantities but which may have value as a service completion. According to our records the well referenced above has been shut-in for 6 months or longer. 43 CFR 3162.3-4 (C) requires that wells incapable of production in paying quantities be promptly plugged and abandoned and requires approval for any well temporarily abandoned for more than 30 days.

Therefore your Sundry Notices are being accepted for record purposes and will not be approved. You need to submit a plan for these wells within in 90 days and do one of the following with each well, at a rate of 2 wells per month.

1. Return the well to production or beneficial use.
2. Submit notice of intent to plug and abandon.

Corrective Action to be Completed as follows:

If you decide to **plug and abandon** the well, submit a Sundry Notice (form 3160-5, original and 5 copies) describe the proposed plugging program.

If you decide to **return the well to production**, submit a Sundry Notice (form 3160-5, original and 5 copies) of intent. Include the date you anticipated the well being placed back in service. 43 CFR 3162.4-1(c) also requires you to notify the Authorized officer, not later than the fifth business day after production is resumed for any well which has been off production for more than 90 days, the date on which such production was resumed. Notification may be by letter or Sundry Notice, or orally followed by letter or Sundry Notice.

If the well is to be used for **beneficial purposes**, submit a Sundry Notice (Form 3160-5, original and 5 copies) include information concerning future use. A brief description of your proposed plans and economic feasibility and an anticipated date for placing the well in beneficial use will suffice. Beneficial use includes, but is not limited to, recompletion to other horizons, conversion to injection for secondary or enhanced recovery, and salt-water disposal or injection.