Form 3160-5 (February 2005)

1 Type of Well

3a Address

TYPE OF SUBMISSION

\_\_Notice of Intent

✓ Subsequent Report

2 Name of Operator TRILOGY OPERATING, INC

4 Location of Well (Footage, Sec., T., R., M., or Survey Description) 2230' FWL & 2428' FSL, SECTION 7, T19S, R39E

P.O. BOX 7606, MIDLAND, TEXAS 79708

## OCD-HOBBS UNITED STATES

## SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED
OMB No 1004-0137
Expires March 31, 2007

	UNITED STATES DEPARTMENT OF THE INTI BUREAU OF LAND MANAGEN	FORM APPROVED OMB No 1004-0137 Expires March 31, 2007	
SUNDRY Do not use ti	NOTICES AND REPORT	TS ON WELLS	NMNM99058 6 If Indian, Allottee or Tribe Name
SUBMIT IN TR	ell. Use Form 3160-3 (APD)  IPLICATE- Other instruction	7 If Unit or CA/Agreement, Name and/or No N/A	
me of Operator TRILOGY	Gas Well Other  OPERATING, INC	8 Well Name and No. NATALIE FEDERAL # 1 9 API Well No.	
ddress . BOX 7606, MIDLAND, 7 cation of Well (Footage, Sec.)	TEXAS 79708 3b 1 T, R, M, or Survey Description)	Phone No (include area code) 32/686-2027	30-025-37736  10 Field and Pool, or Exploratory Area NADINE BLINEBRY  11 County or Parish, State
12 CHECK A	-	GATE MATURE OF NOTICE	LEA COUNTY, NEW MEXICO
YPE OF SUBMISSION	PPROPRIATE BOX(ES) TO INDI	TYPE OF ACTION	REFORT, OR OTHER DATA
If the proposal is to deepen dir Attach the Bond under which following completion of the in- testing has been completed. F determined that the site is read 9/15/07 - RUWL and run 9/20/07 - Perforate lower swab back acid I	Alter Casing  Casing Repair  Change Plans  Change Plans  Convert to Injection  Planted Operation (clearly state all pertinent de rectionally or recomplete horizontally, give the work will be performed or provide the avolved operations. If the operation results inal Abandonment Notices must be filed only for final inspection)  CBL - good cement to surface, PBTI Blinebry from 6414'-6422', 6432'-643', and, no shows of oil or gas - POOH versions.	Reclamation  I Recomplete Recompl	162
9/25/07 - Acidize w/ 2000	gals 15% NEFE, swab back load w/	light gas blow and trace of oil, deci	ide to frac el @ 25 bpm & 4800 psi, SWI to let gel break
	and and put well into production to t	, 5 6	
10/31/07 - Production test	t of middle Blinebry yields 3 BOPD +	- 40 BWPD + 3 MCFD, prepare to	add upper Blinebry - wait on rig
I hereby certify that the for Name (Printed/Typed) MICHAEL G M		Title ENGINEER	
Signature M	MMonn	Date	11/06/2007

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)	1				
MICHAEL G MOONEY	Title El	NGINEER			
Signature MM MMonny	Date		11/06/2007		
THIS SPACE FOR FEDERA	L OR S	TATE OFFICE	USE M	AR II 3 2008	
Approved by Chie Welliams OC DISTRIC	T SUP	VISOR/GENE	ACCERT	D FOR R	ECORI
Conditions of approval, if any, are attached. Approval of this notice does not war certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	lease Of	ffice		-0 1 000	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for a States any false, fictitious or fraudulent statements or representations as to any materials.	ny person kno iter within its	owingly and willfully jurisdiction	y to make to any dep	artinent or agency of	f the United
(Instructions on page 2)			BUREAU C CARLS	F LAND MANA BBAD FIELD OF	AGEMENT FICE

Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
_OM B No 1004-0137
Expires March 31, 2007

L	ease	Serial	No	

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			NMNM99058		
			6. If Indian, Allottee or Tribe Name		
			N/A		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7 If Unit or CA/Agreement, Name and/or No		
1 Type of Well			N/A		
	er 		8. Well Name and No.		
2 Name of Operator Trilogy Operating, Inc			NATALIE FEDERAL # 1 9 API Well No		
3a Address	3b. Phone No. (i	nclude area code)	30-025-37736		
P.O. Box 7405, Midland, Texas 79708	432/686-2027	7	10 Field and Pool, or Exploratory Area		
4 Location of Well (Footage, Sec., T., R., M., or Survey Description	on)		NADINE BLINEBRY  11. County or Parish, State		
2230' FWL & 2428' FSL, Section 7, T19S, R39E					
			LEA COUNTY, NEW MEXICO		
12. CHECK APPROPRIATE BOX(ES)	TO INDICATE NA	ATURE OF NOTICE	E, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION		TYPE OF ACTIO			
Notice of Intent	Deepen	Production	n (Staturk time) United Turbit		
And Casing	Fracture Treat	Reclamati			
Subsequent Report Casing Repair Change Plans	New Construc Plug and Aban	— · · · · · · · · · · · · · · · · · · ·	LOther lly Abandon IAN - 8 2008		
Final Abandonment Notice Convert to Injection	Plug Back	Water Dis	1,7,3,1		
13. Describe Proposed or Completed Operation (clearly state all	nertinent details includir	ng estimated starting dat	te of the property was a standard to the property of the prope		
If the proposal is to deepen directionally or recomplete horizon	ontally, give subsurface le	ocations and measured a	and true vertical depths of all pertinent markers and zones		
Attach the Bond under which the work will be performed or	provide the Bond No on	file with BLM/BIA F	Required subsequent reports shall be filed within 30 days		
following completion of the involved operations If the operations	tion results in a multiple	completion or recompl	etion in a new interval, a Form 3160-4 shall be filed once		
testing has been completed. Final Abandonment Notices sha determined that the site is ready for final inspection.)	ll be filed only after all re	equirements, including i	reclamation, have been completed, and the operator has		
11/09/07 - MIRU pulling unit, POOH w/ rods & tbg.	set RBP @ 6284' to 1	test upper Blinebry I	Formation, RUWL and perforate from 6178'-6190'.		
6194'-6206', 6226'-6240', 6248'-6256' @ 2	spf = 92 holes, Run th	og & pkr, swab dry -	order out acid		
11/10/07 - Acidize w/ 3500 gals 15% NEFE, breakdo put well on pump to get production test	wn @ 3920 psi, excell	lent ball action, ISIP	= 2865 psi, 15 min = 2731 psi, swab back acid load		
11/16/07 - Test upper Blinebry w/ 0 BO + 109 BW +	0 MCF, Rw=0.28@69	9, prepare to abando	on zone		
12/02/07 - MIRU pulling unit, POOH w/ prod eqpt,	POOH w/ RBP , RUV	VL and set CIBP @	6130' and dump bail 30' of cement on top of plug		
perforate the Glorietta Formation from 58	10'-5813', & 5824'-28	8  w/  4spf = 28  holes,	swab test for results		
12/04/07 - Glorietta Zone producing 200 bpd sulfer	vater, POOH w/ prod	l eqpt, abandon zone	w/ CIBP set @ 5700', dump bail 30' of cement on		
top of plug, perforate the Holt Zone from	5304'-5306' & 5312' v	v/ 4 sp1 = 16 holes, sv	wab test w/ gas shows, decide to test on pump		
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)	1		١ .		
MICHAEL G MOONEY	Tit	le ENGINEER			
Signature May My Moren	Da	te	12/21/2007		
THIS SPACE FO	R FEDERAL O	R STATE OFFI	CEUSENTATION DATE OF THE COLUMN		
	C DISTRICT SUP				
Approved by		_ Title	Date MAR 0 3 2008		
certify that the applicant holds legal or equitable title to those right		Office	1441 - 2222		
which would entitle the applicant to conduct operations thereon	JAN 5 2008				

Title 18 USC Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction

(Instructions on page 2)

BURFAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

any hepatiment or agency of the United