Submit 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		Form C-103 Revised June 10, 2003	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30 025 01130	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Type of L	ease
District III			STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Le	ease No.
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Un	it Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			New Mexico –BG- State NCT 1	
PROPOSALS.)			8. Well Number	
1. Type of Well:	Oil Well X Gas Well Other (Injection)		02	
2. Name of Operator			9. OGRID Number	
CrownQuest Operating, LLC			213190	
3. Address of Operator			10. Pool name or Wildcat:	
P.O. Box 53310, Midland, TX 79710			Saunders Permo Pe	enn
4. Well Location (Surface)				
Unit Letter M: _660_feet from the _South _line and _660`_feet from the _West_line				
Section 14 Township	14S Range 33E	NMPM Lea	County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.): 4206 GR				
12 Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBS			SEQUENT REPO	RT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORLD			K AL	TERING CASING 🗌
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS PLUG AND ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		
OTHER:		quent - T/A		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
11-29-07: MIRU. NDWH & NU BOP. TIH w/ 140 joints 2 3/8" tubing, 17# scraper & bit.				
11-30-07. Tagged up with 315 joints. Pull out of hole and shut down for weekend.				
12-3-07: RIH w/CIBP and 309 joint tubing. Set CIBP @ 9660' and rigged up pump truck. Circulated 220 bbls fresh water with packer				
fluid. Pressure and test casing to 500 psi. Casing did not hold. Shut down for night. 12-4-07: Pulled tubing, loaded & tested casing; pressure tested to 550 psi, lost 100 psi – well will not pass MIT test. Shut-in.				
Preparing plugging procedure for submission to Oil Conservation Division.				
I tohuling hindbing hissoring to promission to our compartment artificial.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE				
Type or print name Ann E. Ritchie E-mail address: ann.ritchie@wtor.net Telephone No. 432 684-6381				
(This space for State use)				
Conditions of approval, if any:				

JAN 1 0 2008

HOBBS OCD