Submit 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resource	Form C-103 May 27, 2004
1625 N. French Dr , Hobbs, NM 88240	Energy, minerals and reaction resource	WELL API NO. 30-025-10287
District II 1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	STATE FEE X  6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	,	o. State on a Gas Bease No.
SUNDRY NOT (DO NOT USE THIS FORM FOR PROP	CICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	
1. Type of Well: Oil Well	Gas Well  OtherSWD	8. Well Number 4
	Operating Inc.	9. OGRID Number 147179
3. Address of Operator 2010 Ra Midland	nkin Hwy , TX 79701	10. Pool name or Wildcat San Andres
4. Well Location		
Unit Letter K		
Section 15	Township 22S Range 37E	NMPM CountyLea
	11. Elevation (Show whether DR, RKB, RT, Gas 3385 GR	R, etc.)
Pit or Below-grade Tank Application	or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water		
Pit Liner Thickness: m		ls; Construction Material
	PLUG AND ABANDON ☐ REMEDIAL	SUBSEQUENT REPORT OF: WORK   ALTERING CASING
TEMPORARILY ABANDON  PULL OR ALTER CASING	·	E DRILLING OPNS.□ P AND A 🛛 EMENT JOB □
FULL OR ALTER CASING	MOLTIFLE COMPL GASING/CL	
OTHER:	Detect operations (Clearly state all pertinent data	ils, and give pertinent dates, including estimated date
		ns: Attach wellbore diagram of proposed completion
	block, TAG @ 1388, PU 6" bit, 6-3 1/2" drill coll	ars & 39 jts of tbg. Break CIRCU, drill out salt
	ut 5' of cmt to 3785, TIH @ perforate @ 3532.	
2/7/08. TIH w/100 jts 2 3/8 tbg, set 7" pkr @ 3290. 2/8/08. Pump 50 sx plug in & out @ 3532.		
2/9/08. TIH & tag cmt plug @ 3360, PU to 1053 & set pkr, perf through tbg @ 1275, sqz 50 sx cmt, 25 sx in & 25 sx out, WOC. 2/12/08. TIH, re-squeeze @ 1275 w/50 sx cmt, WOC, TIH & tag plug @ 1125, TIH & perf squeeze holes @ 285, set pkr @ 30'.		
2/12/08. T1H, re-squeeze @ 12/5 2/13/08. Pump 85 sx cmt in perfs	w/50 sx cmt, wOC, 11H & tag plug @ 1125, 11H @ 285 around 8 5/8 to surf leave 7" full of cmt.	& perf squeeze holes @ 285, set pkr @ 30'.
2/16/08. Cut off WH & dead men	, install dry hole marker. Final report. Well is P&A	AECENED
Location has been cleaned and is	ready for inspection.	
Approved for plugging of well bore only. Liability under bond is retained pending re		FEB 2 2 2008
of C-103 (Subsequent Report of Well Plugg which may be found at OCD Web Page und	ing) of Condition was sent Report of Well Plugging) er when a ser of bond at OCD Web Page under	HADDEACH
Forms, www.cmntd.state.nm.us/ocd.	Former was a smard attenum.us/ocd.	HOBBS OCD
	a above is true and complete to the best of my kno	
SIGNATURE		wledge and belief. I further certify that any pit or below- mit  or an (attached) alternative OCD-approved plan .
		mit 🗍 or an (attached) alternative OCD-approved plan 🗍 .
Type or print name Shay Stricklin For State Use Only	TITLE Regulatory Tech	in@chkenergy.com  Telephone No. (432)687-2992
For State Use Only	or closed according to NMOCD guidelines [3], a general per	in@chkenergy.com  Telephone No. (432)687-2992