Submit 3 Copies To Appropriate District Office	State of New Mexico	• ,	Form C-103
District I	Energy, Minerals and Natural Re	sources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		,	WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIV		30-025-21219 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis D	r.	STATE S FEE
District IV	Santa Fe, NM 87505	,	6. State Oil & Gas Lease
1220 S. St. Francis Dr., Santa Fe, NM 87505			58102
SUNDRY NOT	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SÜCH		Flying M San Andres Unit	
PROPOSALS.)		17.	0.777.11.57
	Gas Well ☐ Other ☒ P&A'd		8. Well Number 9-3
2. Name of Operator SOUTHWEST ROYALTIES, INC.			9. OGRID Number
3. Address of Operator		21355 10. Pool name or Wildcat	
6 DESTA DRIVE, STE 2100, MIDLAND, TEXAS 79705		Flying M San Andres	
4. Well Location			, , ,
	.978 feet from the S line a	nd 1993	feet from the E line
Section 16	Township 9S Range 3		NMPM LEA County
	11. Elevation (Show whether DR, RKB,		
	4368' GR		
Pit or Below-grade Tank Application o			
Pit typeDepth to Groundwa		ll Dista	nce from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	struction Material
12. Check A	Appropriate Box to Indicate Nature	of Notice,	Report or Other Data
NOTICE OF IN	TENTION TO:	OUD.	·
NOTICE OF IN		SUB: EDIAL WORK	SEQUENT REPORT OF: ☐ ALTERING CASING ☐
TEMPORARILY ABANDON			LLING OPNS. PANDA
PULL OR ALTER CASING		NG/CEMENT	
OTHER DECEMENT WATER			_
OTHER: PRODUCED WATE		R: Reck	amation
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
			,
REQUEST FOR FINAL INSPECTION	ONI		
REQUEST FOR FINAL INSPECTION	JIN.		
I hereby certify that the information a	above is true and complete to the best of m	y knowledge	and belief. I further certify that any pit or below-
grade tank has been/will be constructed or	closed according to NMOCD guidelines [], a gene	eral permit 🔲 o	r an (attached) alternative OCD-approved plan .
SIGNATURE Au	TITLE OPERA	ATIONS ASS	T DATE 2/29/08
	OI DIO	LITOTIO AOS	Date 1VIOC
Type or print name DAWN M. HC			
For State Use Only	WARD E-mail address howard@cl	aytonwilliam	s.com Telephone No. 432/688-3267
	DWARD E-mail address howard@cl	aytonwilliam	
APPROVED BY:	DWARD E-mail address showard@cl	aytonwilliam J	
APPROVED BY:	DWARD E-mail address Thoward@cl	aytonwilliam	s.com Telephone No. 432/688-3267 DATE <u>03/04/2</u> 008

COMPLIANCE OFFICER



NEW MEXICO ENERGY, MINERALS and RECEIVED NATURAL RESOURCES DEPARTMENTAUG 27 2007

L RICHARDSON
Governor
Joanna Prukop
Cabinet Secretary

Mark E. Fesmire, P.E.
Director
Oil Conservation Division

24-Aug-2007

SOUTHWEST ROYALTIES INC
6 DESTA DRIVE
SUITE 2100
MIDLAND,TX 79705-

Property Name: FLYING M SA UNIT

J-16-9S-33E 30-025-21219-00-00

093

form C-103. Report of Plugging has been approved as

Form C-103, Report of Plugging has been approved as to plugging of the Well Bore. Liability under bond is retained until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

1. All pits have been remediated, filled and leveled.
2. Rat hole and cellar have been filled and leveled.
3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and AP well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
5. The dead men and tie downs have been cut and removed.
6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been remediated, leveled and cleared of all junk & equipment.
7. All environmental concerns have been addressed as per OCD guidelines.
The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected.
When all of the grant and in all share has been done along and office this office by completing alonging and

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Name Dan Now and Title Open Quest 2/29/08