

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P O Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO	30-025-06792
5 Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6 State Oil / Gas Lease No	
7 Lease Name or Unit Agreement Name	S.J SARKEYS 26
8 Well No	2
9 Pool Name or Wildcat	PENROSE SKELLY GRAYBURG
10 Elevation (Show whether DF, RKB, RT,GR, etc)	3395'

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS	
1 Type of Well	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2 Name of Operator	CHEVRON USA INC
3 Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4 Well Location	Unit Letter <u>D</u> : <u>660'</u> Feet From The <u>NORTH</u> Line and <u>660'</u> Feet From The <u>WEST</u> Line Section <u>26</u> Township <u>21-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10 Elevation (Show whether DF, RKB, RT,GR, etc) 3395'	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☒ RETRIEVE FISH, ACIDIZE, SCALE SQUEEZE

12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103

01-23-08: MIRU. REL TAC & FREE TBG 01-24-08. TIH FREE POINT TBG. TAG @ 3735. CUT TBG @ 3716 TIH TO 3400
01-25-08: LATCH ONTO FISH @ 3716. JAR ON FISH. REL FISH TIH W/NEW SET JARS TAG @ 3713. LATCH ONTO FISH. REL FISH TIH W/2 7/8" WS.
01-28-08 LATCH ONTO FISH.UNLATCH FR FISH. 01-30-08 TAG FISH @ 3716 TIH W/RODS & TAG @ 3735.
01-31-08 TAG @ 5811 PUH. FREE POINT @ 5805 CUT TBG OFF @ 5782. 02-01-08. PUH W/FISH. LATCH ONTO FISH FISH CAME LOOSE TIH W/NEW GRAPPLE & WS. 02-04-08. LATCH ONTO FISH @ 5782. JAR ON FISH. MAKE 22"
02-05-08: TIH W/NEW SET JARS & FISHING ASSEMBLY LATCH ONTO FISH @ 5782 JAR ON FISH GAIN 18-20" 02-06-08 TAG @ 5827. C/O TO 5880. 02-07-08 WORK TO LATCH ONTO FISH. TIH W/BIT TO ABOVE PERFS.
02-08-08: TAG @ 5866. C/O SAND FR 5866-6063 FELL OUT. TIH W/WS & TAG @ 6218. C/O 6218-PBTD @ 6275
02-11-08: TIH W/RBP & PKR SET RBP @ 5918 PUH SET PKR @ 5649 ACIDIZE LOWER BLINEBRY PERFS 5742-5822 W/900 GALS 15% NEFE HCL. SET RBP @ 5650 SET PKR @ 5460 ACIDIZE UPPER BLINEBRY PERFS 5519-5558 W/3300 GALS 15% NEFE3 HCL. REL PKR LATCH ONTO RBP SET RBP @ 5918. PUH & SET PKR @ 5460. 2-12-08 SWABBING. PMP 50 BBLS W/2 DRUMS SCALE INHIB LATCH ONTO RBP & PUH TO 3975 SET RBP. TIH W/PKR TO ABOVE PERFS 2-13-08 MARK SETTINGS PUH SET PKRS IN BLANK PIPE ACIDIZE PERFS 3675-3876 W/4550 GALS 15% NEFE HCL. REL PKR PUH TO 3620 02-14-08: SWABBING 2-18-08 SCALE SQZ W/4420 GALS SCALE INHIB. SET PKR @ 3620 2-19-08 LATCH ONTO RBP @ 3975. REL RBP TIH W/CIBP & SET @ 5425 2-20-08: PU 2 7/8" TBG 2-21-08 TIH W/INSERT PUMP & RODS. LOAD & TEST. RIG DOWN. FINAL REPORT

THIS WELL IS PRODUCING ONLY FROM THE GRAYBURG AT THIS TIME CIBP SET @ 5425'

RECEIVED

MAR 05 2008

HOBBS OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist

DATE 3/4/2008

TYPE OR PRINT NAME Denise Pinkerton

Telephone No 432-687-7375

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY

TITLE

OCD DISTRICT SUPERVISOR/GENERAL MANAGER

DATE

MAR 18 2008

DeSoto/Nichols 12-93 ver 1.0