

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO	30-025-33598
5 Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6 State Oil / Gas Lease No	
7 Lease Name or Unit Agreement Name	STATE 'A-26'
8 Well No	6
9 Pool Name or Wildcat	MONUMENT ABO

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.	
1 Type of Well	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2 Name of Operator	CHEVRON USA INC
3 Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4 Well Location	Unit Letter M 410' Feet From The SOUTH Line and 330' Feet From The WEST Line Section 26 Township 19-S Range 36-E NMPM LEA COUNTY
10 Elevation (Show whether DF, RKB, RT, GR, etc)	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☒ ADD ABO PERFS, ACID STIM, UPSIZE PUMP

12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-03-07. MIRU. 12-05-07. CHANGE FROM 2 3/8" TO 2 7/8" TOOLS. 12-06-07 TIH & TAG @ 7289 RBP @ 7295 12-07-07 TIH W/FISHING TOOL.
12-10-07: TIH W/TBG. TAG TOF @ 7290. TIH W/RETR HEAD & TAG @ 7290 COULD NOT LATCH RBP. 12-11-07 DRILL TORQUE UP. MADE 14 INCHES. 12-12-07: REL RBP. 12-13-07: TIH W/TBG & BIT. TAG @ 7458. PUH W/BIT ABOVE ALL PERFS. 12-14-07 C/O TO 7500
12-17-07 PERF 7151-60, 7375-82, 7394-7420
12-18-07. ACIDIZE PERFS 7375-7420 W/2000 GALS 15% HCL. REL PKR. RAN THRU PERFS. PUH W/PKR & SET @ 7340. 12-19-07. SWABBING.
12-20-07 REL PKR & RBP. PUH W/RBP @ 7340 SET. PUH W/PKR. RESET PKR. RBP COULDN'T GET TEST PUH ABOVE ALL PERFS. TIH W/PKR & RBP SET @ 7340
12-21-07: PUH W/PKR @ 7170 PUMP 800 GALS 15% HCL
12-26-07 SWABBING REL PKR. TIH TO LATCH ONTO RBP. PULL UP TO 7180 SET RBP. PULL PKR UP TO 7175. REL PKR. PULL UP TO 7083. SET PKR. 12-27-07 ACIDIZE ABO PERFS 7151-60, W/1000 GALS 15% HCL. 12-28-07: SWABBING 01-02-08: REL PKR & REL RBP.
1-03-08. TIH W/2 3/8" TBG 1-07-08 PUMP 20 BBLS 10# DN CSG TO KILL GAS. 1-08-08: OPEN WELL TIH W/SUB PUMP.
01-09-08: TIH W/SUB. LAND TBG. RIG DOWN. FINAL REPORT

RECEIVED

JAN 15 2008

HOBBS OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE *Denise Pinkerton* TITLE Regulatory Specialist

DATE 1/14/2008

TYPE OR PRINT NAME Denise Pinkerton

Telephone No 432-687-7375

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY

TITLE OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE

MAR 18 2008

DeSoto/Nichols 12-93 ver 1.0