|  | State of New Mexico  | Form C-103   |
|--|--|--|
| Office District I  | Energy, Minerals and Natural Resour  | rces May 27, 2004  |
| 1625 N. French Dr., Hobbs, NM 88240  |  | WELL API NO.   |
| <u>District II</u><br>1301 W. Grand Ave., Artesia, NM 88210  | OIL CONSERVATION DIVISION  | ON 30-005-00876  |
| District III   | 1220 South St. Francis Dr.   | 5. Indicate Type of Lease  STATE  FEE  |
| 1000 Rio Brazos Rd., Aztec, NM 87410<br>District IV  | Santa Fe, NM 87505   | 6. State Oil & Gas Lease No.   |
| 1220 S. St. Francis Dr., Santa Fe, NM  | ·  | 303375   |
| 87505  | PICES AND DEDODTS ON WELLS   | 7. Lease Name or Unit Agreement Name   |
| (DO NOT USE THIS FORM FOR PROPO  | FICES AND REPORTS ON WELLS<br>OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO<br>ICATION FOR PERMIT" (FORM C-101) FOR SUCH   | Rock Queen Unit  |
| 1. Type of Well: Oil Well  | Gas Well 🛛 Other   | 8. Well Number 39 /  |
| 2. Name of Operator  |  | 9. OGRID Number  |
| Celero Energy II, LP   |  | 247128   |
| 3. Address of Operator   | 1 /TX/ 50504   | 10. Pool name or Wildcat   |
| 400 W. Illinois, Ste 1601, Midlan  | nd, 1 X 79701  | Caprock Queen  |
| 4. Well Location   | ,  |  |
| Unit Letter E :  |  |  |
| Section 26   | Township 13S Range   | 31E NMPM ChavesCounty  |
|  | 11. Elevation (Show whether DR, RKB, RT,   | GR, etc.)  |
| Pit or Below-grade Tank Application  | 4419' GR   | A Company of the Comp |
|  |  |  |
|  | waterDistance from nearest fresh water well  |  |
| Pit Liner Thickness: mi  | Below-Grade Tank: Volume   | bbls; Construction Material  |
| 12. Check  | Appropriate Box to Indicate Nature of N  | Notice, Report or Other Data   |
| NOTICE OF I  | ALTERITION TO  | OUROSOUS DEPORT OF   |
|  | NTENTION TO:   | SUBSEQUENT REPORT OF:  |
| PERFORM REMEDIAL WORK TEMPORARILY ABANDON  |  | AL WORK ALTERING CASING ALTERING ALT |
| PULL OR ALTER CASING   | <u></u>  |  |
|  |  |  |
| FUEL OR ALTER CASING   | , MOETH EL COMILE  | CEMENT JOB   |
| OTHER: Re-Activate proc  | ducer 🗵 OTHER:   |  |
| OTHER: Re-Activate proc<br>13. Describe proposed or com  | ducer  | tails, and give pertinent dates, including estimated date  |
| OTHER: Re-Activate proc<br>13. Describe proposed or compost starting any proposed w  | ducer  |  |
| OTHER: Re-Activate proc<br>13. Describe proposed or com  | ducer  | tails, and give pertinent dates, including estimated date  |
| OTHER: Re-Activate process  13. Describe proposed or composed was or recompletion.   | ducer  | tails, and give pertinent dates, including estimated date  |
| OTHER: Re-Activate process  13. Describe proposed or composed or starting any proposed was or recompletion.  1. MIRU Well Service Rig  | ducer   OTHER: pleted operations. (Clearly state all pertinent devork). SEE RULE 1103. For Multiple Completi   | tails, and give pertinent dates, including estimated date  |
| OTHER: Re-Activate proceed or composed or recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump &  | ducer   OTHER: pleted operations. (Clearly state all pertinent devork). SEE RULE 1103. For Multiple Completi   | tails, and give pertinent dates, including estimated date  |
| OTHER: Re-Activate proceed or composed or composed or recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity   | ducer   OTHER: pleted operations. (Clearly state all pertinent devork). SEE RULE 1103. For Multiple Completi   | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion   |
| OTHER: Re-Activate process  13. Describe proposed or composed of starting any proposed was or recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log  | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  | tails, and give pertinent dates, including estimated date  |
| OTHER: Re-Activate process  13. Describe proposed or composed of starting any proposed was or recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip   | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  leepen 34' to fully evaluate Queen Sand   | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion   |
| OTHER: Re-Activate process  13. Describe proposed or composed of starting any proposed was or recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log  | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  leepen 34' to fully evaluate Queen Sand   | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion   |
| OTHER: Re-Activate process  13. Describe proposed or composed of starting any proposed was or recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip   | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  leepen 34' to fully evaluate Queen Sand   | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion   |
| OTHER: Re-Activate process  13. Describe proposed or composed was or recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip 7. Return well to production   | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  leepen 34' to fully evaluate Queen Sand   | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008   |
| OTHER: Re-Activate process  13. Describe proposed or composed of starting any proposed was or recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip 7. Return well to production  Conditions of Approval:   | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  leepen 34' to fully evaluate Queen Sand oment   | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion   |
| OTHER: Re-Activate process  13. Describe proposed or composed or composed or composed was proposed was propos | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  leepen 34' to fully evaluate Queen Sand oment  n  complete a 24 hours production test usest for Allowable before producting   | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008   |
| OTHER: Re-Activate process  13. Describe proposed or composed or starting any proposed water or recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip 7. Return well to production  Conditions of Approval: OCD requires the Operator to cand submit on form C-104 Requires well Accompanied by Sub   | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  leepen 34' to fully evaluate Queen Sand oment  n  complete a 24 hours production test uest for Allowable before producting sequent report on C-103with dates  | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008   |
| OTHER: Re-Activate process  13. Describe proposed or composed or composed or composed was proposed was propos | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  leepen 34' to fully evaluate Queen Sand oment  n  complete a 24 hours production test uest for Allowable before producting sequent report on C-103with dates  | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008   |
| OTHER: Re-Activate process  13. Describe proposed or composed of starting any proposed wor recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip 7. Return well to production  Conditions of Approval: OCD requires the Operator to cand submit on form C-104 Requires well Accompanied by Suband what was done, along with   | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completing production tbg  leepen 34' to fully evaluate Queen Sand leepen 34' to | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008  HOBBS OCD  |
| OTHER: Re-Activate process  13. Describe proposed or composed of starting any proposed wor recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip 7. Return well to production  Conditions of Approval: OCD requires the Operator to cand submit on form C-104 Requires well Accompanied by Suband what was done, along with   | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completion to production to production to production to production to product at a second part of the production test usest for Allowable before producting sequent report on C-103 with dates tubing size and depth above is true and complete to the best of my known above is true | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008  HOBBS OCD  |
| OTHER: Re-Activate process  13. Describe proposed or composed of starting any proposed wor recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip 7. Return well to production  Conditions of Approval: OCD requires the Operator to cand submit on form C-104 Requires well Accompanied by Suband what was done, along with   | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completion to production to production to production to production to product at a second part of the production test usest for Allowable before producting sequent report on C-103 with dates tubing size and depth above is true and complete to the best of my known above is true | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008  HOBBS OCD  |
| OTHER: Re-Activate process  13. Describe proposed or composed or composed or composed or composed was proposed was propose | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  leepen 34' to fully evaluate Queen Sand oment  complete a 24 hours production test uest for Allowable before producting sequent report on C-103with dates tubing size and depth  above is true and complete to the best of my kr r closed according to NMOCD guidelines , a general p   | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008  HOBBS OCD  Towledge and belief. I further certify that any pit or below-permit or an (attached) alternative OCD-approved plan  |
| OTHER: Re-Activate process  13. Describe proposed or composed of starting any proposed wor recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip 7. Return well to production  Conditions of Approval: OCD requires the Operator to cand submit on form C-104 Requires well Accompanied by Suband what was done, along with   | pleted operations. (Clearly state all pertinent de vork). SEE RULE 1103. For Multiple Completi production tbg  leepen 34' to fully evaluate Queen Sand oment  complete a 24 hours production test uest for Allowable before producting sequent report on C-103with dates tubing size and depth  above is true and complete to the best of my kr r closed according to NMOCD guidelines , a general p   | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008  HOBBS OCD  |
| OTHER: Re-Activate process  13. Describe proposed or composed or composed or composed or composed was proposed was propose | pleted operations. (Clearly state all pertinent devork). SEE RULE 1103. For Multiple Complete production tbg  leepen 34' to fully evaluate Queen Sand poment  n  complete a 24 hours production test usest for Allowable before producting sequent report on C-103with dates tubing size and depth  a above is true and complete to the best of my kr r closed according to NMOCD guidelines , a general public depth  TITLE Operation   | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008  HOBBS OCD  Towledge and belief. I further certify that any pit or belownermit or an (attached) alternative OCD-approved plan   |
| OTHER: Re-Activate process  13. Describe proposed or composed or c | pleted operations. (Clearly state all pertinent devork). SEE RULE 1103. For Multiple Complete production tbg  leepen 34' to fully evaluate Queen Sand poment  n  complete a 24 hours production test usest for Allowable before producting sequent report on C-103with dates tubing size and depth  a above is true and complete to the best of my known to the complete of the comple | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008 HOBBS OCD  Towledge and belief. I further certify that any pit or belownermit or an (attached) alternative OCD-approved plan of the proposed completion.  The proposed completion of the proposed |
| 13. Describe proposed or compost starting any proposed wor recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip 7. Return well to production  Conditions of Approval: OCD requires the Operator to cand submit on form C-104 Requires this well. Accompanied by Suband what was done, along with  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE.  Type or print name. Haylie Urian For State Use Only   | pleted operations. (Clearly state all pertinent devork). SEE RULE 1103. For Multiple Complete production tbg  leepen 34' to fully evaluate Queen Sand poment  n  complete a 24 hours production test usest for Allowable before producting sequent report on C-103with dates tubing size and depth  a above is true and complete to the best of my known of the closed according to NMOCD guidelines , a general part of the closed according to NMOCD guidelines , a general part of the closed according to NMOCD guidelines .  E-mail address: hurias@celeroenerge  | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008  HOBBS OCD  Towledge and belief. I further certify that any pit or belownermit or an (attached) alternative OCD-approved plan of the proposed plan of the proposed completion.  The second of the proposed completion of the |
| 13. Describe proposed or compost starting any proposed wor recompletion.  1. MIRU Well Service Rig 2. TOOH w/ rods, pump & 3. Verify casing integrity 4. Clean out well to TD & d 5. Run Gr/CCL/CN Log 6. TIH w/ production equip 7. Return well to production  Conditions of Approval: OCD requires the Operator to cand submit on form C-104 Requires well Accompanied by Suband what was done, along with  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name  Haylie Urian   | pleted operations. (Clearly state all pertinent devork). SEE RULE 1103. For Multiple Complete production tbg  leepen 34' to fully evaluate Queen Sand poment  n  complete a 24 hours production test usest for Allowable before producting sequent report on C-103with dates tubing size and depth  a above is true and complete to the best of my known to the complete of the comple | tails, and give pertinent dates, including estimated date ions: Attach wellbore diagram of proposed completion  FEB - 5 2008  HOBBS OCD  Towledge and belief. I further certify that any pit or belownermit or an (attached) alternative OCD-approved plan of the proposed plan of the proposed completion.  The second of the proposed completion of the |