Submit 3 Copies To Appropriate District Office	State of N				Form C-103
District I	Energy, Minerals a	ınd Natur	al Resources	WELLADING	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		;		WELL API NO. 30-025-00285	
1301 W. Grand Ave., Artesia, NM 88210					Lease
District III 1220 South St. Francis Dr.			cis Dr.	5. Indicate Type of STATE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> Santa Fe, NM 87505				6. State Oil & Gas	
1220 S. St. Francis Dr., Santa Fe, NM				303735	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or I	Jnit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Rock Queen Unit	
1. Type of Well: Oil Well Gas Well Other Injection				8. Well Number	108 /
2. Name of Operator				9. OGRID Number	
Celero Energy II, LP				247128	
3. Address of Operator				10. Pool name or Wildcat	
400 W. Illinois, Ste 1601, Midland, TX 79701				Caprock Queen	
4. Well Location					
	60'feet from theS			_feet from theE	astline
Section 19		13S	Range 32E	NMPM	Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
Pit or Below-grade Tank Application or	Closure	4365' G	iL .		
		ost froch wa	tor wall Dista	nce from nearest surface	water
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK					LTERING CASING
TEMPORARILY ABANDON					ANDA
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMEN				<del></del>	_
	•	_			_
OTHER: Reactivate Injector	-4-J(C11		OTHER:		· 1 1:
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
1. MIRU Well Service Rig					
2. Fish injection pkr and tailpip	ne out of wellbore @ 2798	ζ,	FFF F		ZA.
3. Verify casing integrity				CEIVE	<b>D</b>
4. Clean out well to PBTD @ 3080' +/-					
5. Run CBL log from PBTD @				EED 0.0.000	,
<ul><li>6. Acidize the Queen Sand inte</li><li>7. RIH w/ injection equipment</li></ul>				FEB 22 2008	
8. Run Integrity Test 9. Place well on injection  Striot To Test  Striot To Test					
9. Place well on injection	money of	-1) 2	TWO FIL	idda U	
	serior to	Jan	<b>&gt;</b>		
I hereby certify that the information a	bove is true and complete	to the bes	at of my knowledge	and belief. I further	ertify that any pit or below-
grade tank has been/will be constructed or c	losed according to NMOCD gu	uidelines 🗌	, a general permit 📋 o	r an (attached) alternati	ve OCD-approved plan □.
SIGNATURE Loylo	Mis T	ITLE	Operations Tech	DATE	2/18/2008
Type or print name For State Use Only  Haylie Urias	E-mail address:	hurias@c	eleroenergy.com		432-686-1883 Ext. 120
					MAR 2 8 2008
APPROVED BY: Conditions of Approval (if any):	T	ITLE_C	peologist		MAR 2 8 2008